

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b> 0005106	<b>CLAIM STATUS</b> Authorized	
BASDEN RV CENTER INC	<b>CLAIM</b> 2399989	
DBA AMERICAN RV CENTER	<b>CLAIM ORIGIN</b> WEB	
600 E BASELINE ROAD	<b>ORIGINAL CLAIM ID</b>	
EVANSVILLE, IN 47725	<b>VIN</b> 4X4TCKE25TK096785	
USA	<b>CHASSIS VIN</b>	
	<b>MILEAGE</b> 0	
<b>Labor rate:</b> \$185.00	<b>SITE/WAREHOUSE</b> 094 / 094A	
<b>OWNER INFORMATION</b>	<b>ITEM #</b> CKT29NM-94	
	<b>DEALER RO #</b> 77393	
	<b>CLAIM START DATE</b> 08/13/2025	
	<b>CLAIM END DATE</b> 01/01/1900	

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**

<b>Operation Code</b>	<b>Operational Description</b>		
20-66-02-00-000664	Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2025-08-13 09:40:44 :: ADJUST THE FRONT DOOR NOT SHUTTING Front door not shutting The front door wouldn't shut due to screw being stripped so moved the striker plate and also moved where screw is now will shut and open properly			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b> \$55.50
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$55.50
<b>Notes</b>			

### Labor

**Line# 2**

<b>Operation Code</b>	<b>Operational Description</b>		
20-66-02-00-000664	Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2025-08-13 09:47:10 :: ADJUST REAR DOOR NOT SHUTTING Rear door Rear door wouldn't shut due to screw being stripped so moved the striker plate and also moved where screw is now will shut and open properly			
<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.30	<b>Sub Labor Amt</b> \$55.50
<b>Serial#</b>	<b>Appr Hrs</b>	0.30	<b>Appr Labor Amt</b> \$55.50
<b>Notes</b>			

### Labor

**Line# 3**

<b>Operation Code</b>	<b>Operational Description</b>		
20-55-01-00-003684	Awning Roller Tube - Exterior/Awnings - Electrical (Carefree of Colorado)/ Replace/No Tread Code		
<b>Complaint, Cause, Correction</b>			
Original Note : bhoffman@americanrvcenter.com, 2025-08-13 09:49:46 :: THE AWNING LOOKS LIKE IT IS LEANING TO ONE SIDE Awning bowed When bringing in awning or taking it out you can see the tube inside is bowed and needs replaced Awning tube is 15foot wide black			
<b>Model#</b> NA	<b>Dlr Sub Hrs</b>	1.50	<b>Sub Labor Amt</b> \$277.50
<b>Serial#</b> NA	<b>Appr Hrs</b>	0.00	<b>Appr Labor Amt</b> \$0.00
<b>Notes</b>			
sent to vendor thank you Case #6131020 regarding 2399989 : 4X4TCKE25TK096785 - BASDEN RV CENTER INC			

Thank you for contacting the Lippert Customer Care Center. Case #6131020 has been created in response to your submission.

Whether you're reaching us to order parts, request technical assistance or receive general customer service, we will be in touch with you within the next 24 hours. Additional resources are

