



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77393
Promised Date:
20 AUG 25

CUSTOMER WORK ORDER

WO #: 77393

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0822 BH TO CLOSE

Stock #: 11645
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE GREY WOLF 29NM
Chassis #: 4X4TCKE25TK096785
Serial #: 4X4TCKE25TK096785
Mileage: 0
Licence:

Invoice #:
Date In: 26 JUL 25
Promised: 30 AUG 25
Date Sched:
Completed: 22 AUG 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: I brought unit in and leveled unit then hooked to city water conection and pressurized the system to check for leaks in the put water in fresh tank and made sure the pump works properly then dewinterized unit and made sure all tank sensors, water outlets/inlets were working properly and not leaking I then removed lp tanks off the front of unit and took to fill both tanks i then put tanks back on unit and made sure appliances on lp were working properly (water heater, gas range, furnace) then did lp drop test to make sure the regulator was at the right pressure then made sure there were no leaks in the system with a 5 minute hold test then made sure all 120 volt outlets, water heater, microwave, refrigerator, air-conditioner were working properly then made sure all 12 volt power lights, speakers, radio, awning, leveling system, range hood, USB, USB-C outlets were all working properly

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ADJUST THE FRONT DOOR NOT SHUTTING

CAUSE: Front door not shutting

CORRECTION: The front door wouldn't shut due to screw being stripped so moved the striker plate and also moved where screw is now will shut and open properly

Labor

Code	Description	Mechanic	Total
------	-------------	----------	-------



Customer #: 1000
BASDEN'S AMERICAN RV,



Z990 MISC LABOUR CODE (EXTERNAL) JLC 55.50

Subtotal for Job #1: 55.50

Job #2 - Warranty

COMPLAINT: ADJUST REAR DOOR NOT SHUTTING

CAUSE: Rear door

CORRECTION: Rear door wouldn't shut due to screw being stripped so moved the striker plate and also moved where screw is now will shut and open properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50
Subtotal for Job #2:			55.50

Job #3 - Warranty

COMPLAINT: THE AWNING LOOKS LIKE IT IS LEANING TO ONE SIDE

CAUSE: Awning bowed

CORRECTION: When bringing in awning or taking it out you can see the tube inside is bowed and needs replaced

Awning tube is 15foot wide black

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: THE MINI DOOR ON THE DOOR SIDE WILL NOT SHUT AND NEEDS ADJUSTED

CAUSE: Rear door

CORRECTION: Rear door wouldn't shut due to screw being stripped so moved the striker plate and also moved where screw is now will shut and open properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50
Subtotal for Job #4:			55.50

Job #5 - Internal

COMPLAINT: NO TV SIGNAL

CAUSE: Tv not working

CORRECTION: When testing the test tv I didn't have any channels coming through so I thought I had maybe a bad spot in the campertesting it in the living room so I moved the test tv to the main bedroom and tested in there had the same issue so then I took the box down from the ceiling to check all the wires and none were unplugged nor were any of the tempered with so then I checked the wire going from the back of the the test tv to the end of the connector and found the test tv wire was damaged or it was tampered with so I went over to another technician and had them come over and help me build a new coax cable as well as a new connector for the testing of the tv reception after plugging in the new coax and new cable I immediately got the channels I didn't have before so knowing that I went around to all the outlets and noticed I have channels everywhere knowing that my issue was resolved

W/O: 77393
Promised Date: 30 AUG 25



Customer #: 1000
BASDENS AMERICAN RV,



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C

Subtotal for Job #5: 0.00

Parts Total: 0.00

Labour Total: 166.50

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 166.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 22 Aug 2025

W/O: 77393
Promised Date: 30 AUG 25



Customer #: 1000
BASDEN'S AMERICAN RV,

