



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

WO: 77416
Promised Date:
20 AUG 25

CUSTOMER WORK ORDER

WO #: 77416

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0915 BH TO CLOSE

Stock #: 11646

Stock Desc: 2026 TT ALLIANCE RV

DELTA 292RL

Chassis #: 7M5TD3320TC307179

Serial #: 7M5TD3320TC307179

Mileage: 0

Licence:

Invoice #:

Date In: 29 JUL 25

Promised: 30 AUG 25

Date Sched:

Completed: 27 SEP 25

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*77693 on 29 AUG 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

CAUSE: New PDI

CORRECTION: Torqued all lug nuts to 110 ft lbs. Installed battery box. Checked all exterior clearance lights and break lights. Checked emergency brake to be working as well as regular brakes. Took off lp tanks and brought to filling station to fill. Found low point cold water valve broken. Had a work order put in. All interior lights work. Noticed kitchen sink has low pressure. A work order was put in for it. All other facets, toilet, and shower run well on city. Filled fresh tank and ran water pump. Water pump was not working correctly and a work order was put in. Did an lp drop test and camper passed. Held lock up at 8wsi for 5mins. Tested tv and it does turn on but did not get a good signal in bay. Model and serial numbers documented on appliances. Microwave, fridge, range top, stove, water heater, and furnace all working correctly. both ac work and blew cool air. Inspected roof and found seals in good condition. Inspected outside seals around v light and doors to be in good condition. City connection/ tank fill and black tank flush in good condition. Dump valves working properly. Outlets to be in working order. All drawers and cabinets open and close properly. Lights on couch work. Remote for front ac working properly. Electric heater working properly fan and light above range top working correctly. All plumbing drains well. Drain valves working properly. Tire pressure on all tires brought to 80psi. Found scratch on entry door work order put in. Parts request put in for door decal as well. Gfi I'm camper were not working so a work order was put in.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal


COMPLAINT: ADJUST ENTRY DOOR.DOESN'T OPEN AND CLOSE CORRECTLY

CAUSE: Adjust entry door



Customer #: 1000
BASDEN'S AMERICAN RV,





CORRECTION: Noticed striker plate was not making good contact with lock. Moved striker plate a adjusted lock screws. Door opens and closes properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Subtotal for Job #1:			0.00

Job #2 - Warranty

COMPLAINT: THE COLD WATER LOW POINT DRAIN VALVE IS BROKEN

CAUSE: Broken low point valve

CORRECTION: Saw low point valve had broken. Removed old valve and replaced with new

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Parts

Part #	Description	Qty	Price	Total
30879	30879 Shut Off Valve; PEXLock; Stop	1.00	8.99	8.99

Subtotal for Job #2: 45.99

Job #3 - Internal

COMPLAINT: THE KITCHEN FAUCET IS NOT FLOWING

CAUSE: Kitchen faucet not working.

CORRECTION: During pdi of the unit I noticed the kitchen faucet was not working. Would not flow when connected to city water or on water pump. Pictures taken parts request put in

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
24212	Faucet - Kitchen - Bullet Pulldown -	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS FREIGHT - JOBS 3,6	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: THE PUMP IS NOT WORKING RIGHT

CAUSE: Pump not working

CORRECTION: During pdi of the unit noticed the water pump wouldn't work. Would only pulse and never run correctly. Pictures taken parts request put in

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	92.50

Parts

Part #	Description	Qty	Price	Total
333426	Pump - Water - Revolution - 12V - 3 GPM - 55 PSI	1.00	57.28	57.28



Subtotal for Job #4: 149.78

Job #5 - Internal

COMPLAINT: THE TV OUTLET BEHIND THE FIREPLACE IS NOT WORKING.

CAUSE: Tv outlet not working

CORRECTION: Tested wire from outlet to box and was not running power tested gfi in bathroom with no power checked breaker box and found miss labeled and flipped correct breaker. Gfi has power

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: SCATCH ON BOTTOM LEFT CORNER OF ENTRY DOOR

CAUSE: Scratch on entry door glass

CORRECTION: During pdi of the unit I noticed scratches on, the glass of entry door. Pictures taken and parts request put in. New door arrived removed screws in old door after taking screw cover off. Removed screws inside door. Once screws were out slowly worked door loose from putty. Once putty was loose removed door. Excess putty was still on unit removed what was possible with putty knife and use mineral spirits to get rest of putty up. Putty mad a lot of mess on unit and had to clean up blac, marks all around door of unit. Removed silicone around top of door. Once all putty and silicone was removed unboxed door. Added putty to new door and stuck to unit. Ran a couple screws in unit to make sure it was square. Once it was checked ran rest of screws in door. Once all screws were in ran screw cover over both sides of door. Once screw cover was on added top ring and shoot screws in to secure to door. Added decal with soapy water to attach to door. Ran bubbles out and soaked outside of decal as well let sit over night to stich to door. Cut excess screw cover off. Adjusted steps latch to new door. Siliconed top ring of door. Door open and shuts well

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	185.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts Part #	Description	Qty	Price	Total
32530	Door - Entry - 28 x 72 - RH - Glass	1.00	406.99	406.99
33614	DECAL - DOOR LGND - DELTA 2026	1.00	8.28	8.28
PUTTY	PUTTY TAPE - ROLL	1.00	7.49	7.49
326192	76IN SNAP TRIM SCREW COVER, BLACK (CUT TO LENGTH)	2.00	9.87	19.74

Subtotal for Job #6: 627.50

Parts Total: 508.77
 Labour Total: 314.50
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 823.27

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Sep 2025

W/O: 77416
Promised Date: 30 AUG 25



Customer #: 1000
BASDEN'S AMERICAN RV,



Customer Work
Order

