

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77466
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 55849 - CLAY HOPKINS
Address: 999 NEED
EVANSVILLE, IN
47725

Phone:

Stock Number: 2023 SALEM

VIN:

HIN:

SER#: 4X4TSMJ29P8070164

Mileage:

Work Order Comp: 24 SEP 25

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 05 AUG 25

Inv #: 422444

WO # Job # Description JOB INFORMATION

77466 1 GREY TANK IS LEAKING
Replace rear Grey Tank.
Retrieved unit. Retrieved new Tank. Spoke with Ben and went thru
Email to clarify which Grey tank it was and its the rear.
Removed underbelly. Disconnected the Tank Sensors. Hooked up dump
tube and Lowered the front of trailer to empty the remaining slug
from tank. Disconnected the Grey Tank Scissor valve bolt and nuts
to free Dump tub at that point. Cut support straps. Removed the
frontside bracket. Located and removed inside panels to gain
access to where drains and vent pipe goes into tank. From the way
manufacturer built the unit it was extremely difficult to remove
the 3 pipes coming into to Tank but with some maneuvering, prying
and leverage i got pipes to come out allowing for the backside of
tank to clear the rear support bracket (which is not removable,
its welded)! Dropped tank and took measurements to make hole cuts
in new tank and installed rubber pipe grommets. Installing tank
was even more difficulties but i managed to get Pipes to slide
into grommets and used to jack to support tank in place while i
installed the frontside support bracket. Looked my piping over
from tank to scissor valve and saved what parts i could but ended
up needing 2 90 degree Male to Females, Rubber sleeve, and
reducer. Parts department has all parts except the 2 90 degree
elbows. Installed the reducer on tank and reassembled the scissor
valve side with the Rubber Sleeve. Reinstalled the Tank Sensors.
Reinstalled the Underbelly. Put inside panels back into place.
And put slideroom back in. Waiting on the 90 degree elbows to

Claim : 77466

```
*****
WO #      Job #   Description      JOB INFORMATION
*****
                finish job.
```

```
*****
Part No    Job#   Description      PARTS      Qty    Price    Total
*****
60P14964A   1   TANK, HOLDING, BLACK, 24" W X 63"  1.00    96.40    96.40
3673        1   1.5" FERNCO COUPLER                1.00     9.87     9.87
20490       1   T1041-1 TANK ADAPTOR                1.00     4.16     4.16
89-8353     1   1-1/2" STREET ELBOW                 2.00     5.99    11.98
```

```
*****
Lab Code   Job#   Description      LABOUR      Hrs    Rate    Total
*****
Z990       1   MISC LABOUR CODE (EXTERNAL)        1.00   185.00   185.00
Z990       1   MISC LABOUR CODE (EXTERNAL)        3.50   185.00   647.50
Z990       1   MISC LABOUR CODE (EXTERNAL)        1.50   185.00   277.50
```

```
*****
Excode     Job#   Description      EXTRAS      Qty    Price    Total
*****
FRT        1   UPS-HOLDING TANK                1.00   126.44   126.44
```

```
Parts Total:      122.41
Labour Total:     1,110.00
Sublet Total:      0.00
Extras Total:     126.44
```

>>>> Claim Total: 1,358.85

Customer Signature: _____

Date: _____