

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77467
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 55215 - DONALD WEBER
Address: 1408 MOCKINGBIRD VALLEY GREEN
LOUISVILLE, KY
40207
Phone: 502-741-6961
Stock Number: 11479 - 2025 PARADIGM 295MK 7M5FP3427SB205501
VIN: 7M5FP3427SB205501 HIN: SER#: 7M5FP3427SB205501
Mileage: 0 Work Order Comp: 10 SEP 25
Auth. No: Dealer #:
Warr. Date: 15 OCT 24 Work Order Date: 05 AUG 25 Inv #: 422056

WO # Job # Description JOB INFORMATION

77467 1 PLUMBING UNDER KITCHEN SINK KEEPS COMING APART. THIS IS AT THE
JOINT AT THE P-TRAP. IT LOOKS LIKE THE DRAIN PIPE COMING OFF OF
THE SINK IS TOO SHORT.
The pipe is too short. Sent in parts request.
Recieved new drain pise assembly. Cut pipe to length. Installed
new drain pipe.

77467 4 STRIP OF WALLPER PEELING GOING UP STEPS TO BEDROOM
Seam tape is damaged. We don't have this color here. Sent parts
request

77467 9 CUSTOMER ADVISES THAT THE TOILET IS NOT HOLDING WATER.
The seal isn't holding water. Replaced the inner seal and the
toilet still won't hold. The flapper is moving down away from
the seal. I can move it up but it folds back down immediately.
Tech suggests replacing the toilet.

77467 2 REMOVE EXCESS GLUE ON WOOD SURFACES IN CAMPER.
Glue needs to be removed
Applied mineral spirits to a rag and cleaned glue off of table
tops and drawer.

77467 10 CUSTOMER ADVISES THAT THE LATCH THAT HOLDS THE SCREEN DOOR AND
THE MAIN DOOR TOGETHER IS NOT HOLDING THE TWO DOORS TOGETHER.
The latch isn't holding the door when you open it.
Moved the door latch down to hold the door.

Claim : 77467

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
77467      11     THE DOOR SIDE SLIDE TOPPER IS LOOSER THAN THE OTHERS AND IT HOLDS
              A LOT OF WATER WHEN IT RAINS.
              Moved a lift over to the unit. Ran slide room out. The front of
              the fabric is a little loose. THE FACTORY INSTALLED THE THE SLIDE
              TOPPER RAIL INCORRECTLY. THERE IS NO PITCH TO THE FABRIC WHICH IS
              WHY ITS HOLDING WATER.
              Ran the awning on the slide room out. Pinned both sides of the
              slide topper. Removed mounting screws from the hardware so I could
              slide the topper over to wind the spring. Wound the spring
              another 3 turns. Installed brackets and mounting screws. Ran the
              slide room in and out to check function. The material has
              tightened up a little on the front. The fabric will likely hold
              water due to the installation.

77467      12     THERE ARE SOME SCREWS THAT KEEP COMING LOOSE AND HANGING DOWN ON
              THE UNDERSIDE OF THE FIFTH WHEEL OVERHANG.
              Screws are loose
              Tightened the screws.

77467      15     FIND OUT WHY THE LANDING GEAR IS NOT WORKING
              foound wires loose on the trombetta.

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
25011/288787  1     SINK DRAIN W/ADAPTER      1.00      13.21      13.21
23283         4     23283 Tape - Seam - 1 - Jaunt 10.00      0.12      1.20
385311658     9     310 seal                  1.00      34.24      34.24
11769         9     Toilet - Dometic 310 - White - Ch 1.00     185.46     185.46

```

```

*****
Lab Code     Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990         1     MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990         1     MISC LABOUR CODE (EXTERNAL)      0.30     185.00     55.50
Z990         1     MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990         1     MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990         4     MISC LABOUR CODE (EXTERNAL)      0.13     185.00     24.05
Z990         4     MISC LABOUR CODE (EXTERNAL)      0.07     185.00     12.95
Z990         4     MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990         9     MISC LABOUR CODE (EXTERNAL)      0.15     185.00     27.75
Z990         9     MISC LABOUR CODE (EXTERNAL)      0.60     185.00    111.00
Z990         2     MISC LABOUR CODE (EXTERNAL)      0.20     185.00     37.00
Z990        10     MISC LABOUR CODE (EXTERNAL)      0.10     185.00     18.50
Z990        11     MISC LABOUR CODE (EXTERNAL)      0.00     185.00      0.00
Z990        11     MISC LABOUR CODE (EXTERNAL)      0.10     185.00     18.50

```

Claim : 77467

Lab Code	Job#	Description	LABOUR	Hrs	Rate

Z990	11	MISC LABOUR CODE (EXTERNAL)		0.60	185.00
Z990	12	MISC LABOUR CODE (EXTERNAL)		0.10	185.00
Z990	15	MISC LABOUR CODE (EXTERNAL)		0.20	185.00
					37.00

Excode	Job#	Description	EXTRAS	Qty	Price

FRT	9	FED-EX - TOILET		1.00	26.73
					26.73

Parts Total: 234.11
Labour Total: 471.75
Sublet Total: 0.00
Extras Total: 26.73
>>>> Claim Total: 732.59

Customer Signature: _____
Date: _____