

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
 CLAIM 2408696
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2CAEC9SK010847
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 203 / 203
 ITEM # BCAT164BHX
 DEALER RO # 77501
 CLAIM START DATE 08/20/2025
 CLAIM END DATE 01/01/1900

Labor rate: \$185.00

OWNER INFORMATION

KRISTIN MANN
 231 CEDARWOOD DR
 Madison, IN 47250
 USA

Retail Date of Purchase 08/08/2025

WARRANTY EXPIRATION DATE 08/08/2026

Claim Line Details

Labor

Line# 1	Operation Code 40-132-24-11-001433	Operational Description Roof AC Control Box Wire Connection, any - Electrical/Low Voltage Wiring/ Repair/Electrical
---------	---------------------------------------	---

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-08-20 16:30:58 :: THE AIR CONDITIONER THERMOSTAT IS READING AN F1 CODE Two of the cables for the air conditioner unit were not hooked up to the control board. I removed the lower platem. Opened up the control board box and found that the data wires were not hooked up to the control board. The harness had been left inside the upper air conditioner unit. I pulled the harness down and plugged it into the control board. I tested the air conditioner, and now it is working as it should.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00

Notes

Labor

Line# 2	Operation Code 60-136-01-00-001480	Operational Description City Water Connection - Plumbing/Fresh Water Supply/Replace/No Tread Code
---------	---------------------------------------	--

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-08-20 16:31:44 :: CITY WATER CAME OUT OF THE BACK WALL The water ports on the back wall only had 2 screws holding them to the wall. They had been mounted off center. I removed both water ports and added putty tape behind the ring. I then shifted the port to the center of the hole. I screwed the ports back to the wall and sealed them up.

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt \$55.50

Notes

Submitted	Labor Amt	\$92.50			
	Parts & Freight	\$0.00			
	Total	\$92.50			

Approved	Labor Amt	\$92.50			
	Parts & Freight	\$0.00			
	Total	\$92.50			

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.