



Warranty Authorization Form

Date: 8/20/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 102456 Unit: 7M5TD292XTC307174
Series: Delta Model: 2026DEL262RB
Notes: 8/19/2025 Paul-Please see line 2 for pending issue.
Status: Approved

Dealer Information

American RV (812) 867-5200 cbruce@americanrvcenter.com	Basden RV Center, Inc. DBA/ American RV 600 E Baseline Rd Evansville, IN 47725	Requestor: Ben Hoffman Return Fax #: Email: bhoffman@americanrvcenter.com
--	--	---

Operation Line 1

Flat Rate Code: 20038 SPRAY PORT - REPLACE (part return in US) Fault Code: VENDOR

Serial #: Model #: Notes:

Problem: SPRAY PORT ON THE BACK OF THE CAMPER THE CAP WILL NOT STAY ON

Cause: Broken spray port

Remedy: The back spray port was broken. When removed saw that pex line was rubbing against black tank. Added right angles to go around black tank to keep from flexing pex line and breaking

Part Return Req: Yes

Status: Approved

Time Requested: .2

Time Allowed: .2

Sublet Repairs: 0.00

Operation Line 2

Flat Rate Code: 20075B WATER PUMP - REPLACE (Photo of model/ serial number) Fault Code: VENDOR

Serial #: Model #: Notes: 8/19/2025 Paul- The picture is not clear..cannot read...cannot make out model and serial numbers

Problem: CHECK PUMP not working right

Cause: the pump was short cycling and it is also installed upside down

Remedy: replace the pump and it stopped short cycling changed to a different pump

Part Return Req: No

Status: Approved

Time Requested: .5

Time Allowed: .5

Sublet Repairs: 0.00



Warranty Authorization Form

Date: 8/20/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 102456 Unit: 7M5TD292XTC307174
Series: Delta Model: 2026DEL262RB
Notes: 8/19/2025 Paul-Please see line 2 for pending issue.
Status: Approved

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 20038 SPRAY PORT - REPLACE (part return in Fault Code: VENDOR US)

Serial #:

Model #:

Notes:

Problem: SPRAY PORT ON THE BACK OF THE CAMPER THE CAP WILL NOT STAY ON

Cause: Broken spray port

Remedy: The back spray port was broken. When removed saw that pex line was rubbing against black tank. Added right angles to go around black tank to keep from flexing pex line and breaking

Part Return Req: Yes

Status: Approved

Time Requested: .2

Time Allowed: .2

Sublet Repairs: 0.00

Operation Line 2

Flat Rate Code: 20075B WATER PUMP - REPLACE (Photo of model/ serial number) Fault Code: VENDOR

Serial #:

Model #:

Notes: 8/19/2025 Paul- The picture is not clear..cannot read...cannot make out model and serial numbers

Problem: CHECK PUMP not working right

Cause: the pump was short cycling and it is also installed upside down

Remedy: replace the pump and it stopped short cycling changed to a different pump

Part Return Req: No

Status: Approved

Time Requested: .5

Time Allowed: .5

Sublet Repairs: 0.00