

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2403881
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TRLH28P1904302
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	010 / 010C
OWNER INFORMATION		ITEM #	RLT8332SB
ANITA & CHARLES FRAZIER		DEALER RO #	77531
8516 Bramblewood Ln		CLAIM START DATE	08/15/2025
Evansville, IN 47725		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/27/2025	WARRANTY EXPIRATION DATE	06/27/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-08-15 16:29:07 :: THE REFRIGERATOR WILL GET COLD WHEN ON SHORE POWER, BUT WHEN CUSTOMER DISCONNECTS FROM SHORE AND HOOKS TO THE TRUCK, THE REFRIGERATOR SHUTS OFF INSTANTLY. Ground to inverter not hooked up and hidd3n UNDER the Battery Box. Checked Fridge to see the type of fridge and amp draw it is. Checked the 7way plug and wiring of battery disconnect and any inline fuses and automatic resettable breakers... which all checked out good. Found Inverter in front compartment and had to remove wire stabilizer strap, and mount to remove to panel to pull voltage which had none. Tracked down the power wires from inverter and found the ground was strapped all the way under the Battery Box. I wirednthe ground to the battery and now have power to the Inverter. Reinstalled Inverter panel and inverter to wall. Returned all other Covers, brackets and mounts. Double tested Fridge on Inverter power and it does work.			
Model#		Dlr Sub Hrs	1.60	Sub Labor Amt \$296.00
Serial#		Appr Hrs	1.60	Appr Labor Amt \$296.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	40-197-01-11-001419	110 Volt Exterior Refrigerator Outlet - Electrical/110 Volt Exterior/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-08-15 16:31:47 :: THE GFCI PLUG IN THE BEDROOM IS BRITTLE AND CRACKES. Replace broken receptical Removed cover to GFCI in bedroom and can visually see where the mount of receptical is broken and cracking. Needs new receptical. Received new receptical from parts and installed.			
Model#		Dlr Sub Hrs	0.30	Sub Labor Amt \$55.50
Serial#		Appr Hrs	0.30	Appr Labor Amt \$55.50
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	40-196-01-11-001309	Charging Center - USB & 12 Volt - Electrical/12 Volt Interior/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-08-15 16:32:43 :: THE USB CHARGER IN THE BEDROOM IS NOT WORKING Bad circuit board. Removed USB port from mount and tested at both the crimped connection and wires going into the circuit board itself... both had 13v. Issue is in the circuit board. Needs a new USB Port. Received new USB port, the cutout the manufacturer cut to mount port was to large, so i had to center it the best i			

could.

Model#

Dlr Sub Hrs

0.40

Sub Labor Amt \$74.00

Serial#

Appr Hrs

0.40

Appr Labor Amt \$74.00

Notes

Submitted

Labor Amt

\$425.50

Parts & Freight

\$0.00

Total

\$425.50

Approved

Labor Amt

\$425.50

Parts & Freight

\$0.00

Total

\$425.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.