



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77533
Promised Date:
20 AUG 25



Customer #: 54580
RAVEN, MARK



CUSTOMER WORK ORDER

WO #: 77533 (Appointment Date: 12 AUG 2025 - Time: 11:30am)

Customer: 54580 - RAVEN, MARK -
701-230-2030

Tag:

Author: BH

Location: 0825 CHECK WORK

Stock #:

Stock Desc: 2025 5W KEYSTONE

COUGAR 2700BH

Chassis #:

Serial #: 4YDFCGN25S2500504

Mileage:

Licence:

Invoice #: 421381

Date In: 12 AUG 25

Promised: 30 AUG 25

Date Sched:

Completed: 21 AUG 25

Warr. Date:

Job #1 - External

COMPLAINT: THE LIVING AREA A/C IS MAKING A NOISE BUT IT IS COOLING AND VERY NOISEY AND SOME TIMES THE COMPRESSOR SOMETIMES MAKE A LOUD NOISE WHEN STARTING

CAUSE: turned on ac and let run. i didnt hear anything trip on any loud noises come from the unit.

CORRECTION: no correction

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THERE IS A PANEL IN THE SLIDE WEHRE THE REFRIGERATOR IS THAT FALLS DOWN EVERY TIME HE TOWS IT.

CAUSE: The panel is flexing and is pushing away from the wall. The panel is resting on the ceiling of the slide room and is also pushing the panel down.

CORRECTION: Removed the dinette frame away from the panel. Pulled the panel and removed all the staples. Cut the panel shorter on the top. The support on the ceiling is not secured to the ceiling and isnt very strong. Added a new support and secured it. Found a piece of batten strip and ripped it to length because we didn't have the right size. Installed panel with Brad nails. Installed batten strip. Filled holes with putty. Installed dinette frame. Cleaned up area and tools. Typed notes

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	90.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	270.00

Subtotal for Job #2: 360.00

Job #3 - Warranty

COMPLAINT: CHECK THE BRACKET ON THE SLIDE ROOM WITH THE FRIDGE TO THE LEFT MARKED WITH TAPE IT IS NOT FLUSH LIKE THE OTHERS ARE AND MAKE THE SLIDE NOT COMALL THE WAY OUT



W/O: 77533
Promised Date: 30 AUG 25



Customer #: 54580
RAVEN, MARK



CAUSE: The brackets aren't exactly the same on the top and bottom on the rear of the room. The bottom bracket does have a slight gap at the bottom. Service writer is going to contact warranty for instructions or recommendations.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	14.40
Z990	MISCELLANEOUS REPAIR	ZMS	7.20
Z990	MISCELLANEOUS REPAIR	ZMS	68.40

Subtotal for Job #3: 90.00

Job #4 - Warranty

COMPLAINT: THE PANEL ABOVE THE COUCH MARKED WITH BLUE TAPE IS LOOSE AND NEEDS FIXED

CAUSE: Panel is loose.

CORRECTION: Secured panel with Brad nails and filled holes with putty.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	36.00

Subtotal for Job #4: 36.00

Parts Total: 0.00
Labour Total: 486.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 486.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 21 Aug 2025

