



Pre- Authorization number	PREAUTH952 Reference no.77534 5 (PA03904085	Status	Approv ed
---------------------------------	---	--------	--------------

Servicing Dealer 1194 **Name** Basden's American RV **Address** 600 E Baseline Rd
Evansville, IN 47725 **VIN** 4YDFRPW39NR800368 **Retail sold on** 4/30/2022

Root	Approved					Actual	Base	
Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
7143942A	23-439 Fuel Pump Controller 0	1	1			1	1	Complaint: 23-439 Fuel Pump Controller Recall The remedy is to protect the fuel pump controller from the elements of weather by installing a plastic cover on the back side of the skirt metal, and to make sure the circuit is protected by a 15 amp ATC fuse at the Cause: Sent parts request for a new fuel gauge and cover. Fuel pump controller recall Correction: Got the part in and hooked up and the plastic cover put on the under side and spray foamed the top and put budle tape on the cover. And works properly now

Pre-Authorization number: PREAUTH9525 1

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.