



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77583
Promised Date:
00 AUG 25



Customer #: 11000
LAUDERDALE, DAVID K.



CUSTOMER WORK ORDER

WO #: 77583

Customer: 11000 - LAUDERDALE, DAVID
K. - 812-454-4323
Tag:
Author: BH
Location: DELIVERY 0829

Stock #: 11633
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT 164BHX
Chassis #: 5ZT2CAEC0SK011692
Serial #: 5ZT2CAEC0SK011692
Mileage:
Licence:

Invoice #:
Date In: 18 AUG 25
Promised: 29 AUG 25
Date Sched:
Completed: 31 AUG 25
Warr. Date: 29 AUG 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery. Exterior inspection looks good. Roof inspection good i had to replace both vinyl insert in the track at the top. They were about 2in from the end. All good now. Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly had to take the tape off the inside on the shelves and the protective flim on the outside. The freezer door would not shut without hitting. So i put two spacers on the hinge and door shuts like its supposed to. Awning fabric and hardware looks and works properly Awning lights work properly. Tv and antenna works properly ac and furnace works properly. Put 1/3 in the fresh tank and ran the water pump and it worked properly. Had to adjust the bli d behind the couch because it wouldn't stay up. Did my lp drop test on the stove with the water heater and the furnace running. No adjustment needed to the regulator system works properly and no leaks

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2 hitch
Install and set up hitchwork.

CORRECTION: Installed the hitch brakets on the camper and torqued the ball to spec and placed the rest of the hitch in the side compartment
I removed the old hitchwork from the trade. I installed a new hitch on the truck. I set the hitch height and hooked up to the trailer. I adjusted the hitch as needed.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C





Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #HANDLE - Internal

COMPLAINT: INSTALL LEND-A-HAND

CHOOSE BLACK OR WHITE

CAUSE: Install a lend a hand

CORRECTION: Took factory handle off and installed the new Lend a Hand handle and put budle tape behind and sealed with clear silicone

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
2603892	GRAB HANDLE W/GRIP - BLACK - LEND A	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #HANDLE: 0.00

Job #1 - Internal

COMPLAINT: ADD FRONT STAB JACKS

CAUSE: Added stab sack

CORRECTION: Position the two jacks on the front drilled hose and run bolts through and tighten them up jacks work properly.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
285326	24IN SCISSOR JACK KIT WITH CRANK HAN	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #CAMERA - Internal

COMPLAINT: INSTALL WIRELESS CAMERA

CAUSE: Install a wireless camera

CORRECTION: Took off the camera blank and mounted the camera to the housing connected my wires and i taped the plug connector so they dont come apart and pushed the wires in the back wall mounted the camera and the housing to the camper tested it and it works properly then i sealed up the housing was clear silicone.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C



W/O: 77583
Promised Date: 29 AUG 25



Customer #: 11000
LAUDERDALE, DAVID K.



Parts

Part #	Description	Qty	Price	Total
8952	BRAND MOTION 7" CAMERA SYSTEM	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #CAMERA: 0.00

Job #MAXX - Internal

COMPLAINT: ROOF VENT COVER - INSTALLED EACH

CAUSE: Roof vent cover

CORRECTION: Maked it off and mounted the mounting brackets to the roof vent then bolted the cover to it.
Everything works properly

Labor

Code	Description	Mechanic	Total
Z990	INSTALL MAXX AIR VENT	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
40431	CAMCO VENT COVER - WHITE	1.00	N/C	N/C

Subtotal for Job #MAXX: 0.00

Job #2 - Warranty

COMPLAINT: INSERT TRIM HAS SHRUNK

CAUSE: Replace vinyl

CORRECTION: Took out the vinyl insert and replaced it with new both sides and sealed the ends.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Parts

Part #	Description	Qty	Price	Total
E569	E569 HEAVY DUTY INSERT TRIM MOLDING - 1IN X 50FT - BLACK	1.00	12.31	12.31

Subtotal for Job #2: 49.31

Parts Total: 12.31
Labour Total: 37.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 49.31

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Sep 2025

