



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77619
Promised Date:
20 AUG 25

CUSTOMER WORK ORDER

WO #: 77619 (Appointment Date: 22 AUG 2025 - Time: 03:00pm)

Customer: 41759 - WEBER, STEVE -

Tag:

Author: GA

Location: 0902 GA TO CLOSE

Stock #:

Stock Desc: 2014 TT KEYSTONE

PASSPORT 2650BH14

Chassis #:

Serial #: 4YDT2652XET411476

Mileage:

Licence:

Invoice #: 421702

Date In: 22 AUG 25

Promised: 30 AUG 25

Date Sched:

Completed: 29 AUG 25

Warr. Date:

Job #1 - External

COMPLAINT: SLIDE ROOM SOUNDS LIKE A STRIPPED GEAR

CAUSE: Gear box is stripped and making grinding sound.

CORRECTION: Had to remove top facia and took 4 of us to get the room to go out. Then i Replaced gear box and put together motor and then reinstalled the facia.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Parts

Part #	Description	Qty	Price	Total
94-0006	R25076 SLIDE-OUT GEARBOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #16-261 - Warranty

COMPLAINT: THE WIRING TO THE THERMOSTAT WAS NOT INSTALLED CORRECTLY

CORRECTION: checked and made sure wires was connected correctly and tight and no bare wire showing.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BRM	90.00

Subtotal for Job #16-261: 90.00

Parts Total: 0.00
Labour Total: 90.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 90.00



Customer #: 41759
WEBER, STEVE