

FileOrig	Draft	10/09/2025	bhoffman@americanrvcenter.com	<a href="#">View Attachment</a>
FileOrig	Draft	10/09/2025	bhoffman@americanrvcenter.com	<a href="#">View Attachment</a>
Feedback	Denied	10/09/2025	<a href="mailto:kcarter@forestriverinc.com">kcarter@forestriverinc.com</a>	per pictures attached Forest River is not seeing the wall panel is too short Installed correct by plant No repair necessary thank you
Feedback	Feedback	10/09/2025	<a href="mailto:kcarter@forestriverinc.com">kcarter@forestriverinc.com</a>	Good morning Ben heard back from the plant and this was their advise on repairing the door issue please move the middle and bottom hinge in above 1/8 of an inch and may need to adjust striker plate afterwards
Feedback	Authorized	10/09/2025	<a href="mailto:kcarter@forestriverinc.com">kcarter@forestriverinc.com</a>	After reviewing claim with plant, plant requested for this repair to move the bottom and middle hinge attached to the wall from the door over 1/8 of an inch and door would sit flush. Dealer has already done repairs to the wall adding a 3/4 shim behind the wall. Reviewed claim with management, claim authorized .50 for plant instructions for repair. Parts will be reviewed as to pertain to the instuctions by the plant for repair. thank you Repairs were done without authorization by Forest River