

FileOrig	Draft	08/29/2025	bhoffman@americanrvcenter.com	View Attachment
FileOrig	Draft	08/29/2025	bhoffman@americanrvcenter.com	View Attachment
OP change	Draft	08/29/2025	kcarter@forestriverinc.com	
Feedback	Authorized	08/29/2025	kcarter@forestriverinc.com	per pictures attached, please adjust the striker plate so the passage door shuts and closes completely thank you
Feedback	Feedback	08/29/2025	jwylie@forestriverinc.com	sent back at dealers request
FileOrig	Feedback	08/29/2025	bhoffman@americanrvcenter.com	View Attachment
FileOrig	Feedback	08/29/2025	bhoffman@americanrvcenter.com	View Attachment
FileOrig	Feedback	08/29/2025	bhoffman@americanrvcenter.com	View Attachment
FileOrig	Feedback	08/29/2025	bhoffman@americanrvcenter.com	View Attachment
Feedback	Feedback	08/29/2025	bhoffman@americanrvcenter.com	PLEASE REVIEW THE PHOTOS if you cant see where the problem is i can talk to you about it 8128675200 my name is Ben thank you
Feedback	Authorized	08/29/2025	jwylie@forestriverinc.com	Dealer has requested more time than needed. authorized an adequate amount of time to straighten the wall