

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 77663  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11658 - 2026 CATALINA SUMMIT 261BHS 5ZT2CARB2TU047097  
VIN: 5ZT2CARB2TU047097 HIN: SER#: 5ZT2CARB2TU047097  
Mileage: 0 Work Order Comp: 30 AUG 25  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 27 AUG 25 Inv #: 421693

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*

- 77663 1 LIVING ROOM CEILING LIGHT STOPPED WORKING  
Light flickering then not working.  
During pdi i noticed living room light by fridge was flickering then stopped working. Removed screws from light then cut wires to light. Replaced with new light by attaching wires together. Made sure light turns on and it does. Put screws back into light and put cover on.
- 77663 2 GUTTER ON THE DOOR SIDE IS FALLING OFF  
Gutter spout falling off  
During pdi noticed the gutter spout was falling off of camper. Pulled off from spout. Had to removed sealent around gutter and removed to screws from side to be able to put gutter spout back in place. Put screws back in to secure spout and put black non sag where it was removed to access screw.
- 77663 3 WINDOW STRING GOT CAUGHT IN THE WINDOW TRIM RING  
String caught in window ring.  
During pdi i noitced the string for the blings was caught in the window frame ring. Removed the two screws on the side of window. Pulled string out. Placed screws back in. Strings are now free.
- 77663 4 ENTRY DOOR NEEDS ADJUSTED  
Entry door not shutting  
Moved striker plate forward. Still not shutting tight. Saw middle hinge was not as far in as rest. Took a light mallet to strike

Claim : 77663

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*

          hinge. Adjsuted door slightly but was still a little off. Door  
           was also bowed so bent door slightly to try to straighten out.  
           Door shuts better

\*\*\*\*\*  
 Part No      Job#      Description      PARTS      Qty      Price      Total  
 \*\*\*\*\*

479579	1	LED - Mushroom Light - Ultra Brig		1.00	3.02	3.02
3388	2	551LSB-1 BLACK NON SAG DICOR		1.00	8.72	8.72

\*\*\*\*\*  
 Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total  
 \*\*\*\*\*

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.05	185.00	9.25
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50

Parts Total:	11.74
Labour Total:	175.75
Sublet Total:	0.00
Extras Total:	0.00

>>>> Claim Total:      187.49

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_