

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2418136
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB2TU047097
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT261BHS-8
		DEALER RO #	77663
		CLAIM START DATE	08/28/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1

Operation Code	40-196-01-11-001274	Operational Description
Complaint, Cause, Correction	Single Pancake Light - Electrical/12 Volt Interior/Replace/Electrical	
Original Note : bhoffman@americanrvcenter.com, 2025-08-28 16:15:45 :: LIVING ROOM CEILING LIGHT STOPPED WORKING Light flickering then not working. During pdi i noticed living room light by fridge was flickering then stopped working. Removed screws from light then cut wires to light. Replaced with new light by attaching wires together. Made sure light turns on and it does. Put screws back into light and put cover on.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
Notes		

Labor

Line# 2

Operation Code	20-43-01-00-001109	Operational Description
Complaint, Cause, Correction	Gutter Rail - Exterior/Exterior Miscellaneous/Replace/No Tread Code	
Original Note : bhoffman@americanrvcenter.com, 2025-08-28 16:17:45 :: GUTTER ON THE DOOR SIDE IS FALLING OFF Gutter spout falling off During pdi noticed the gutter spout was falling off of camper. Pulled off from spout. Had to removed sealent around gutter and removed to screws from side to be able to put gutter spout back in place. Put screws back in to secure spout and put black non sag where it was removed to access screw.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.30	\$55.50
Serial#	Appr Hrs	Appr Labor Amt
	0.30	\$55.50
Notes		

Labor

Line# 3

Operation Code	20-46-24-00-000721	Operational Description
Complaint, Cause, Correction	Window - Exterior/Windows/Repair/No Tread Code	
Original Note : bhoffman@americanrvcenter.com, 2025-08-28 16:18:36 :: WINDOW STRING GOT CAUGHT IN THE WINDOW TRIM RING String caught in window ring. During pdi i noitced the string for the blings was caught in the window frame ring. Removed the two screws on the side of window. Pulled string out. Placed screws back in. Strings are now free.		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.15	\$27.75
Serial#	Appr Hrs	Appr Labor Amt
	0.15	\$27.75
Notes		
AUTHORIZED AS REQUESTED		

Labor

Line# 4

Operation Code	20-66-02-00-000664	Operational Description
		Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-08-28 16:19:16 :: ENTRY DOOR NEEDS ADJUSTED Entry door not shutting Moved striker plate forward. Still not shutting tight. Saw middle hinge was not as far in as rest. Took a light mallet to strike hinge. Adjsuted door slightly but was still a little off. Door was also bowed so bent door slightly to try to straighten out. Door shuts better

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50

Notes

Submitted	Labor Amt	\$175.75	Approved	Labor Amt	\$175.75
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$175.75		Total	\$175.75

DEALER _____ **DATE** _____
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE

All repairs described have been inspected and are satisfactory.