

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 2450169 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CARB7SU045635 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 103 / 103 ITEM # CAT261BH-8 DEALER RO # 77664 CLAIM START DATE 09/27/2025 CLAIM END DATE 01/01/1900	
Labor rate: \$185.00 OWNER INFORMATION BRADLEY S GILBERT 4711 KUEBLER RD Evansville, IN 47720 USA		
Retail Date of Purchase 08/29/2025	WARRANTY EXPIRATION DATE 08/29/2026	

Claim Line Details

Labor

Line# 1	Operation Code 70-147-01-11-002194 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-09-27 15:08:01 :: NO CHANNELS ON THE TV Antenna no signal After inspection the tv power booster not working so I replaced it and it works properly now	Operational Description TV Power Supply Booster - Appliances/Television/Replace/Electrical <table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Model#</td> <td style="width: 20%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.30</td> <td style="width: 20%;">Sub Labor Amt</td> <td style="width: 20%;">\$55.50</td> </tr> <tr> <td>Serial#</td> <td>Appr Hrs</td> <td>0.30</td> <td>Appr Labor Amt</td> <td>\$55.50</td> </tr> </table> Notes	Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50	Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50								
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50								

Labor

Line# 2	Operation Code 40-106-24-11-001253 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-09-27 15:09:06 :: JACK NOT WORKING Bad ground contact Turned the jack light on and it lit then pushed the button for the jack to go up or down and the jack light went out. Checked the wire at the circuit breaker by removing it and connecting it directly to the battery and still got nothing from the jack motor. Checked the ground where the jack bolts to the coupler. There were washers on top of the star washers. Unbolted one of the bolts and removed the washer but left the star washer in place. Tightened the bolt then pushed the button for the jack motor and it works. With the washer in place, there was not enough ground contact.	Operational Description Exterior 12 Volt Wiring - Electrical/12 Volt Exterior/Repair/Electrical <table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Model#</td> <td style="width: 20%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.30</td> <td style="width: 20%;">Sub Labor Amt</td> <td style="width: 20%;">\$55.50</td> </tr> <tr> <td>Serial#</td> <td>Appr Hrs</td> <td>0.30</td> <td>Appr Labor Amt</td> <td>\$55.50</td> </tr> </table> Notes AUTHORIZED AS REQUESTED	Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50	Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50								
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50								

Submitted	Labor Amt	\$111.00		Approved	Labor Amt	\$111.00
	Parts & Freight	\$0.00			Parts & Freight	\$0.00
	Total	\$111.00			Total	\$111.00

DEALER _____ **DATE** _____
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ **DATE** _____
SIGNATURE
 All repairs described have been inspected and are satisfactory.