



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77676



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 77676

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 1001 CHECK PREAUTH

Stock #: 11661
Stock Desc: 2026 5W ALLIANCE RV
AVENUE 29RL
Chassis #: 7M5FA332XTA011863
Serial #: 7M5FA332XTA011863
Mileage: 0
Licence:

Invoice #:
Date In: 28 AUG 25
Promised:
Date Sched:
Completed: 26 SEP 25
Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CAUSE: New 5W PDI

CORRECTION: Inspected Roof. Inspected cap seals. Inspected Entry and Compartment Doors. Inspected underbelly and closed all valves. Inspected 5W Hookup. Checked and adjusted Tire Pressure and Lug Torque. Checked Runner, Brake, Turn Lights and Brakes and Brake-awayswitch. Checked 4 way plug-in on rear. Filled and inspected LP tank. Ran and checked leveling system. Set water station knobs and hooked up Water hose. Ran sliderooms out and inspected. Ran awnings out and inspected and retracted. Tested compartment switches for slides and awnings. Dewinterized unit. When quick connect hose in water compartment is hooked up it leaks out of the backside of quick connect on faucet side. Replaced leaking faucet. Performed LP DropTest and adjusted regulator. Turned AC and Fridge on. Tested Stovetop, range, Lights and Oven. Tested Fireplace. Tested Tv and Antenna. Tested Microwave. Tested Recepticals and USB ports. Tested all Cabinets, Drawers and Doors. Adjusted Entry door striker plate. Tested Bluetooth Radio. Ch3cked all Furniture features. Checked all Windows and Blinds. Checked all interior Lights. Filled Black and grey Tanks to 2/3 to tested sensors. Removed all packing on Appliances. Dumped tanks. Took all my Serial and model numbers and filled out Paperwork.

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JRK	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JRK	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JRK	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JRK	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: THE QUICK CONNECT LEAKS WHEN IT IS CONNECTED

CAUSE: Leaking out of backside of quick connect

CORRECTION: Replaced faucet.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	92.50

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



10-0134

4" TWO HANDLE FAUCET

1.00

32.92

32.92

Subtotal for Job #1:

125.42

W/O: 77676

Parts Total: 32.92

Labour Total: 92.50

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 125.42

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Sep 2025



Customer #: 1000
BASDEN'S AMERICAN RV,

