



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77718



Customer #: 48240
CARTER, BRENT



CUSTOMER WORK ORDER

WO #: 77718 (Appointment Date: 02 SEP 2025 - Time: 05:30pm)

Customer: 48240 - CARTER, BRENT -
812-626-2014

Tag:

Author: GA

Location: 0910 BH TO CLOSE

Stock #: 11653

Stock Desc: 2026 TT FOREST RIVER

CHEROKEE GREY WOLF 29TE

Chassis #: 4X4TCKE26TX167320

Serial #: 4X4TCKE26TX167320

Mileage:

Licence:

Invoice #:

Date In: 02 SEP 25

Promised:

Date Sched:

Completed: 10 SEP 25

Warr. Date: 29 AUG 25

Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE SHOWER IS LEAKING BY THE TOILET SIDE WHEN TAKING A SHOWER. IT DRAINS PRETTY GOOD WHEN THE SHOWER HEAD IS AIMED TOWARDS THE DRAIN, BUT IS LEAKS WHEN IT HITS THE SIDE.

CAUSE: Shower leaking

CORRECTION: Customer stated shower leaking when water hits the shower doors by toilet. I found one small area that it might be coming from. I put clear silicone in that spot. I couldn't get it to leaking

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE REAR ENTRY DOOR HAS TO BE SLAMMED HARD TO CLOSE.

CAUSE: Back entry door hard to open

CORRECTION: Adjusted the hinge and the striker and door closes properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Subtotal for Job #2: 55.50

Job #3 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE RANGE VENT IS MAKING A VERY LOUD NOISE

CAUSE: Hood fan making noise

CORRECTION: After inspection of the hood fan. The fan blade was hitting on the screen. So i put a shims on the mounting bracket to give the fan blades more clearance. Fan works properly now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50



Subtotal for Job #3: 18.50

Job #4 - Internal

CUSTOMER WOULD LIKE TO SEE ABOUT GETTING A PRICE TO ADD BLINDS TO THE ENTRY DOORS.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #4: 0.00

Job #5 - Internal

COMPLAINT: CUSTOMER WAS UNABLE TO GET THE EMERGENCY EXIT TO OPEN

CAUSE: Exit window wont open

CORRECTION: I opened all 3 exit windows they work properly.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Subtotal for Job #5: 0.00

Job #6 - Internal

COMPLAINT: CUSTOMER ADVISES THAT SLIDE ROOM IS OUT ALL THE WAY THERE IS MORE OF A GAP AT THE BOTTOM THAN THE TOP

CAUSE: Slideroom more of a gap at bottom than top

CORRECTION: After inspection of the slide room. It is within the tolerance of BAL spec.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: ONE OF THE CABINET DOORS ABOVE THE RANGE VENT IS NOT EVEN WITH THE OTHER ONE

CAUSE: Cabinet doors not even

CORRECTION: Adjusted the doors. They are even now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50

Subtotal for Job #7: 18.50

Job #8 - Warranty

COMPLAINT: ONE OF THE CURTAIN RODS AT THE WINDOW BY THE DINETTE BROKE.

CAUSE: Curtain rod broken

CORRECTION: Inspection of the curtain rod found that is broken and put in a parts request. Got the part and replaced the broken one. All good

Customer #: 48240
CARTER, BRENT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts

Part #	Description	Qty	Price	Total
A285	A285 SIDE CURTAIN HOLD DOWN	1.00	5.41	5.41

Subtotal for Job #8: 23.91

Job #9 - Warranty

COMPLAINT: THE 30 AMP OUTLET DOES NOT STAY CLOSED

CAUSE: 30 amp plug wont stay closed

CORRECTION: Inspection of the plug. The factory set it right in the middle of a rib. And then they tightened down the screws and bowed the plastic and the receptacle door wouldn't stay shut. Even when i cut out for the rib. So i got a new receptacle and cut clearance spots for the rib.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Parts

Part #	Description	Qty	Price	Total
5496	A10-30INBKVP 30A POWER INLET - BLACK	1.00	44.33	44.33

Subtotal for Job #9: 99.83

Parts Total: 49.74
Labour Total: 203.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 253.24

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 10 Sep 2025

Customer #: 48240
CARTER, BRENT

