



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77738
Promised Date:
20 AUG 25

CUSTOMER WORK ORDER

WO #: 77738

Customer: 45604 - PARKER, DAVID -
812-228-7268

Tag:

Author: GA

Location: 0904 GA TO CLOSE

Stock #: 11487

Stock Desc: (11487) 2025 KEYSTONE
COUGAR HALF-TON 29RLI

Chassis #: 4YDFCGN2XS2502426

Serial #: 4YDFCGN2XS2502426

Mileage:

Licence:

Invoice #: 421857

Date In: 04 SEP 25

Promised: 30 AUG 25

Date Sched:

Completed: 31 AUG 25

Warr. Date: 18 NOV 24

Job #ROOFT - External

COMPLAINT: INSPECT ROOF AND ROOF SEAMS - CLEAN AND FILL VOIDS. 1 TUBE OF ROOF SEALANT INCLUDED.

CAUSE: Moved a lift over to the unit. The roof is solid, and the majority of the dicor is in good condition. The corners need to be touched up.

CORRECTION: Applied non leveling dicor to the corners. Moved lift

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C
13-1287	NON SELF LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #3 - Warranty

COMPLAINT: FAN IN BATHROOM ROOF VENT DOESN'T COME ON

CAUSE: Fan is inop.

CORRECTION: Removed inside shroud, handle, screen, and switch. Cut wires off of switch. Verified power coming in. Tested continuity on the switch. Hooked up a separate 12 volt battery to the motor, and nothing happened. The motor is bad. Removed the motor from the fan assembly. I received a new motor from parts. Installed the motor onto the metal bracket. Installed switch and secured wires to the motor. Installed fan blade. Secured the switch to the screen. Installed the screen and shroud. The motor is functioning. Cleaned up mess. Placed the motor in the warranty department. Typed notes.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	54.00

Parts

Part #	Description	Qty	Price	Total
--------	-------------	-----	-------	-------



Customer #: 45604
PARKER, DAVID

31-8395

MOTOR 12V

1.00

30.52

30.52

Subtotal for Job #3:**84.52****Job #4 - Internal**

COMPLAINT: LIGHTS IN LIVING ROOM SLIDE DOES NOT COME ON

CAUSE: Lights are inop on slide room.

CORRECTION: Checked fuse panel. The fuse was blown for the lights. Replaced the 15 amp fuse, and the lights are working.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #4:**0.00**

Parts Total: 30.52

Labour Total: 54.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL:**84.52**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 15 Sep 2025

W/O: 77738
Promised Date: 30 AUG 25Customer #: 45604
PARKER, DAVID