



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77751
Promised Date:
20 SEP 25

CUSTOMER WORK ORDER

WO #: 77751 (Appointment Date: 05 SEP 2025 - Time: 09:30am)

Customer: 21435 - EDWARDS, JAMES
R. - 812-309-0641

Tag:
Author: GA

Location: 0918 GA TO GET WITH JRK
ON THIS

Stock #: 11242

Stock Desc: (11242) 2023 KEYSTONE
COUGAR HALF-TON 30BHS

Chassis #: 4YDTCGP25PL500486

Serial #: 4YDTCGP25PL500486

Mileage:

Licence:

Invoice #:

Date In: 05 SEP 25

Promised: 30 SEP 25

Date Sched:

Completed: 18 SEP 25

Warr. Date: 18 AUG 22

Job #1 - External

COMPLAINT: BLACK TANK LEAKS WHEN IT IS OVER FILLED

CAUSE: Bathroom all goestoblack tank

CORRECTION: Customer said when running shower it goes to his black tank only. Put hose in shower and let run. Checked board and it said black tank was full open valve on black tank to make sure board was right. Black tank emptied shower is connected to wrong tank

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: GREY TANK IS PLUMMED TO THE BLACK TANK

CAUSE: Shower is plummed into the black tank.

CORRECTION: Pulled underbelly to see the Tank schematics. Pulled inside water outlets under panels and examined the drain and vents schematics. Brainstormed on how to cut and cap the current Shower drain and routes im gonna run new shower drain and tie into current drain and vent on grey tank. Ben advised me that shower has to go to front grey tank which in that case i have to remove the shower pan to gain access to top of front grey tank. To remove remove shower pan i have to disassemble and remove the entire shower door, liner, drain and fixture. With the way there was only about a 6in x 6in corner of the grey tank that could be tapped into, i pulled the grey tank vent out of tank and Y'd it off at that point. I cut off the manufacturer 4x's 22 degree angled concoction and had to brainstorm and play with angles to clear the subfloor supports and angle it correctly to clear into the small clearance of the wall. After i had my layout planned i marked them with there angles and primed and glued them together. I finagled my new replacement into place and connected it to the vent tube and tank grommet and tightened coupler in place. Positioned Shower pan in place and connected the Ptrap to new drain. Temporarily hooked up shower faucet and water tested drain. Removed faucet. Screws Pan into position. Screwed Liner in place. Installed faucet, wand holder and hose guide back into place. Installed shower door and recaulked all seems i had broken. Cleaned up my mess and tools and wrote my notes.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	540.00



Customer #: 21435
EDWARDS, JAMES R.

Z990 MISC LABOUR CODE (EXTERNAL) JRK 360.00

Parts

Part #	Description	Qty	Price	Total
428004	1.5" PIPE COUPLER	1.00	2.59	2.59
89-8067	90 STREET ELBOW 1 1/2"	1.00	3.81	3.81
11-0369	3 Way Elbow; 1-1/2 Inch Hub; ABS Pla	1.00	13.04	13.04
100815	Fitting - ABS - Str Elbow - 1 1/2" -	3.00	1.51	4.53

Other Services

Code	Description	Qty	Price	Total
PARTS	1.5" SLIP CAP	1.00	4.99	4.99

Subtotal for Job #2: 928.96

Job #3 - External

DOOR CODE IS 47546 ON DEMAND CODE IS 1968

Subtotal for Job #3: 0.00

Job #4 - External

TRIP PLANNED FOR SEPTEMBER 16TH

Subtotal for Job #4: 0.00

Parts Total: 23.97
Labour Total: 900.00
Sublet Total: 0.00
Extras Total: 4.99
WORK ORDER TOTAL: 928.96

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 18 Sep 2025

W/O: 77751
Promised Date: 30 SEP 25



Customer #: 21435
EDWARDS, JAMES R.

