



KEYSTONE

Root Approved Actual

Operation	Description	Sublet	Sub Hours	Hours	hours	Qty	Base hours	Complaint/Cause/Correction
2300102F	Entrance Door - Hinged - Adjust Door or Lock	0	0.2	0.2		1	0.2	Complaint: ENTRY DOOR NEEDS ADJUSTED Cause: Entry door needs adjusted Correction: During pdi noticed entry door was not shutting properly and wouldnt latch. Adjust striker plate by moving bottom end forward and tightened back. Checked and door latches better
4202014B	Awning - Main - Hardware - Inner Arm - Rear	0	0.3	0.2		1	0.2	Complaint: THE AWNING ARM KEEPS GETTING STUCK Cause: Awning arm hanging up Correction: During pdi i noticed awining arm was hanging up. Saw a gap from arm to mount. Took screws out and adjusted over. Arm opens and shuts well.
6104203A	Shower/Tub - Drain - Repair	0	0.5	0.5		1	0.5	Complaint: SHOWER CONNECTION IS LEAKING Cause: Leaking from shower connection Correction: During pdi noticed water was leaking from threads of shower. Took shower head connection off and and cleaned out where threads were. Onced clean out reconnected to shower. Checked for leaks amd non were found.
2315408A	Window - 47" or Less - Seal Glass to Frame	0	0.6	0.2		1	0.2	Complaint: 3 WINDOWS ARE MISSING SEALER Cause: Gaps in windowDuring a pdi noticed gaps in window were it was just metal and no foam. Taped off window and put clear silicone im gap to fill. Ran finger to round off and clean excess silicone off. Correction: During a pdi noticed gaps in window were it was just metal and no foam. Taped off window and put clear silicone im gap to fill. Ran finger to round off and clean excess silicone off.

Pre-Authorization number: PREAUTH23514

1.1

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the
claim form.

The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the
amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH235 14 (PA03917465)	Reference no. 77754	Status	Approved
--------------------------	----------------------------------	---------------------	--------	----------

Servicing Dealer 1194	Name Basden's American RV	Address 600 E Baseline Rd Evansville, IN 47725	VIN 4YDTSGM25T7100857	Retail sold on
-----------------------	---------------------------	---	-----------------------	----------------

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.