

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77788
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 56066 - KATHLEEN BELMONT
Address: 407 E EMMONS ST
ROBINSON, IL
62454

Phone:

Stock Number: 2026 CAMPSIGHT

VIN:

Mileage:

Auth. No:

Warr. Date:

HIN:

SER#: 5ZT2CRRB7TF081717

Work Order Comp: 15 SEP 25

Dealer #:

Work Order Date: 10 SEP 25

Inv #: 422208

WO # Job # Description JOB INFORMATION

77788 1 HOSE UNDER THE BATHROOM SINK HAS COME LOOSE AND IS LEAKING
Loose water connection.
Tightened all 5 connections under bathroom sink. Hooked up City
water connection and touch tested all connections, everything is
dry.

77788 2 CUSTOMER WOULD LIKE US TO CHECK THE INSULATION UNDER BATHROOM
SINK WHERE THE LEAK IS TO MAKE SURE ITS OK

There are multiple areas that customer could be referencing by
the black Tank flush inlet which i added alil more insulation but
has to leave it open enough to inspect connection. They could be
referencing the cutout behind drain and water lines. There is a
small panel on the sink that i found a screw hole in the lower
compartment floor, panel partially covers drain and lines... so
this could be what they are referencing which is in part how they
manufacturer it.

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.07 185.00 12.95
Z990 1 MISC LABOUR CODE (EXTERNAL) 0.44 185.00 81.40
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
Z990 2 MISC LABOUR CODE (EXTERNAL) 0.49 185.00 90.65

Parts Total: 0.00
Labour Total: 185.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 185.00

Customer Signature: _____

Date: _____

Claim : 77788

```

*****
Lab Code  Job#  Description      LABOUR                      Hrs      Rate      Total
*****

```