



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77815
Promised Date:
10 SEP 25

CUSTOMER WORK ORDER

WO #: 77815

Customer: 56194 - GREGORY,
ELIZABETH - 317-370-8287

Tag:

Author: BH

Location: DELIVERY

Stock #: 11520

Stock Desc: 2025 TT COACHMEN APEX
NANO 208BHS

Chassis #: 5ZT2CXKB5SL018503

Serial #: 5ZT2CXKB5SL018503

Mileage:

Licence:

Invoice #:

Date In: 15 SEP 25

Promised: 19 SEP 25

Date Sched:

Completed: 27 SEP 25

Warr. Date: 19 SEP 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Torqued lug nuts to spec running lights and tail lights work properly brakes and Emergency Brakes work properly had to shoot the battery box to camper was not secured and had to get a new battery strap. And installed a new battery. Let air out of all 5 tires and put monster seal in all tires and then put correct air pressure in all 5 tires. Exterior inspection looks good. Roof inspection completed just touched up all screw heads the sealer was sunk in on them. Roof good now. Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly water heater works properly refrigerator works properly Awning lights work properly Awning fabric looks good. Lp-CO detector works properly smoke alarm works properly. Did my lp drop test on outside port with stove and water heater running made a adjustment to regulator but it wasn't enough so i had to replace the lp regulator and the system works properly now. Tv antenna works properly. Put a 1/3 in the fresh tank to run the water pump and it works. Drained black and gray tanks and left 1/3 in the fresh tank for demonstration. Camper good to go.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
55364	55364 REPLACEMENT BATTERY BOX STRAP	1.00	N/C	N/C
06-0443	MEGR-253P LP REGULATOR 2-STAGE	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: Hitch work

The truck needs the hitchwork setup for the trailer.

CORRECTION: Installed the hitch brakets to the camper and i torqued the ball on the hitch head. And put the rest of the hitch in side compartment.
I installed the hitchwork and set the hitch height. I hooked up to the trailer. I adjusted the hhitchwork as needed.



Customer #: 56194
GREGORY, ELIZABETH



Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C
14-2931	90-02-4300 EQUALIZER ADJ HITCH SHANK	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #E2:				0.00

Job #MONSTER - Internal

COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: Monster seal

CORRECTION: Jack up each tire let all the air out and pumped monster seal in each tire and put the correct air pressure in all 5 tires. And put the monster seal stickers on camper. Good to go

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Subtotal for Job #MONSTER:			0.00

Job #1 - Internal

WASHBAY MAXXGAURD

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: LEAK UNDER THE KITCHEN SINK

CAUSE: Leak under kitchen sink

CORRECTION: After inspection of the pipes i found the pipe connectors was loose. So i took them apart and made sure they were clear from debris and put them back together and tightened the connections no leaks now

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50
Subtotal for Job #2:			55.50

Job #3 - Internal

COMPLAINT: FACTORY TOYOTA BRAKE CONTROLLER NOT WORKING

CAUSE: The truck has a factory trailer brake. It is not working.

CORRECTION: I checked the factory trailer brake and it has no output. The fuse is good. The trailer brake is not showing on the dash. The truck acts like the cluster is not programmed for the break control. It needs to go to the dealer to get fixed.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C



W/O: 77815
Promised Date: 19 SEP 25



Customer #: 56194
GREGORY, ELIZABETH



Subtotal for Job #3: 0.00

Job #DELUXE - Internal
DELUXE STARTER KIT

Parts				
Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Parts Total: 0.00
Labour Total: 55.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 55.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Sep 2025

