



Warranty Authorization Form

Date: 10/30/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 105467 Unit: 7M5TD292XTC307174
Series: Delta Model: 2026DEL262RB
Notes: 9/22/25: Danielle -- Sent lines 4 & 5 to the vendor
Status: Approved

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 14069 PANEL - IN SLIDEOUT - WALL - REPAIR *Fault Code:* POOR PERFORMANCE
(Photos required)

Serial #: *Model #:* *Notes:* 10/28/25-SP- THIS IS STILL APPROVED, JUST OPENING LINE SO THEY CAN ADD A LINE TO PA. PER BEN IN SERVICE @ AMERICAN RV

Problem: small wall in the slide room has come apart and cable for the usb charger have come apart and needs to be put back together *Time Requested:* 1
Cause: Bench seat *Time Allowed:* 1
Sublet Repairs: 0.00

Remedy: Removed panel. Removed screws holding front trim. Put screws in new spot. Removed screws on upper trim. Put back in new spot. Stapled back panel and putty holes.

Part Return Req: No
Status: Approved

Operation Line 2

Flat Rate Code: 14009 BLIND - REPLACE (Photo of data tag, defect, and full view required)(Auth required if United Shade) *Fault Code:* PART MISSING

Serial #: *Model #:* *Notes:*

Problem: THERE IS BLIND MISSING NEAR THE SINK AND STOVE (((WINDOW IS 36X15))) *Time Requested:* .5
Cause: Blind/ VALANE *Time Allowed:* .2
Remedy: PARTS MISSING *Sublet Repairs:* 0.00

Part Return Req: No
Status: Approved with Modifications

