

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77827
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 54437 - RONALD WHITTENBURG
Address: 10501 DRIVER DRIVE EVANSVILLE, IN

47725

Phone: 573-429-9330

Stock Number: 11477 - 2025 AVENUE 29RL 7M5FA3323SA009712

VIN: 7M5FA3323SA009712 HIN:

SER#: 7M5FA3323SA009712

Mileage: 0

Work Order Comp: 30 NOV 25

Auth. No:

Dealer #:

Warr. Date: 27 JUN 25

Work Order Date: 16 SEP 25

Inv #: 424970

WO # Job # Description JOB INFORMATION

77827 4 THE THREE SCREWS ON THE ARM REST ARE STRIPPED AND THE ARM REST IS OFF LEVEL AND WHEN SITTING THE RIGHT CHAIR WHEN LOOKING IT FEELS LIKE YOU ARE LEANING
INSTALLD SCREWS FOR THE ARM REST BUT IT FEELS LIKE YOU ARE LEANING WHEN SITTING DOWN
REPLACE THE COUCH installed new couch center arm rest had to remove the seat and install center then i installed the arm to it and then reinstalled the seats and plugged in the charger.
during this i also reinstalled the sewer hangers under the chassis on the outside.

77827 6 THE TOILET IS LEAKING WHEN YOU FLUSH IT MODEL42070
Valve is dripping when foot lever is pushed cripes needs some nugen
installed new valve on the toilet and pressured the system to check for leaks.

77827 9 THE FURNACE WILL COME ON, BUT IT ONLY RUNS FOR ABOUT 3 MINUTES AND THEN SHUTS OFF.
T stat is shutting off the furnace burner after about 10 seconds

tested the lp pressure and it was good so i removed the furnace and put on bench and it worked great i reinstalled and it did not run but about 10 sseconds and burner shut off . i checked the gas line and it was ok no kinks greg mentioined the t stat so we changed the tstat and it worked furnace

Claim : 77827

```

*****
WO #      Job #      Description      JOB INFORMATION
*****
heats now.

77827      10      WHEN LOOKING AT THE COUCH (NOT THE THEATHER SEATING) ONE OF THE
LIGHTS DO NOT COME ON RIGHT SIDE
Light sometimes works sometimes it doesnt
RECCOMMEND TO REPLACE installed new light on walll

77827      14      SPRAY PORT LEAKS WHEN CONNECTED AT THE OFF DOOR SIDE FRONT
Will need a spray port
installed new spray port and pressured to test for leaks

77827      16      THE BED ROOM BLIND ON THE DRIVERS SIDE HAS HOLES IN IT
has holes and needs replaced.
instralled new blind in bedroom on the drivers side window

77827      17      BATHROOM COUNTER TOP HAS A STAIN A CIRCLE

77827      1      WHEN BRING IN SLIDE (1) IT MAKES A NOISE PART OF THE TIME didnt
hear at drop off
could not hear an issue but i noticed the top of the room does
not go out completly

77827      2      THE ENTRY DOOR IS HARD TO SHUT CHECK THE DEAD BOLT
Adjusted the latch
Adjusted the latch.

77827      5      THE LINO ON THE DINNETTE SLIDE IS COMING UP AND WONT LAY DOWN ON
THE FRONT THE SCREW IS CATCHING IT
removed screws and installed flushg screws and trimed bottom of
the facia

77827      11      AWNING (1) THE LEDS LIGHTS ARE NOT TURNING ON
foudn wire pulled from back of the switch

77827      12      THE CABINET DOOR OVER THE COUCH THE RIGHT DOOR IS LOOSE
added ood into hole and then reinstalled screws till tight.

77827      15      TRIM PEICE IN THE PANTY HAS COME LOOSE AND NEEDS REATTACHED
LAYING ON THE FLOOR
trim peice came off the small access panel i glued it in place.

77827      19      INSTALL RV AIR FLOW case 23721 per kyle prater
INSTALL RV AIR FLOW

```

```

*****
Part No      Job#      Description      PARTS      Qty      Price      Total
*****
29857          4      Furniture - 12" Console - Clarend      1.00      158.83      158.83

```

Claim : 77827

Part No	Job#	Description	PARTS	Qty	Price	Total
28213	6	Water Valve - Toilet - Style II -		1.00	14.29	14.29
9201	9	COLEMAN T-STAT BLACK Wall Thermos		1.00	45.49	45.49
15830	10	Light - Interior - Sconce - Brush		1.00	19.28	19.28
21508	14	Faucet - Outdoor - 4" w/2" Shank		1.00	13.83	13.83
23686	16	Shade - Night - 38 x 24 - E Serie		1.00	37.45	37.45
27794	17	Top - Pressed - Luna Crystal - 17		1.00	63.93	63.93

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	9	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	9	MISC LABOUR CODE (EXTERNAL)		1.50	185.00	277.50
Z990	10	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	14	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	16	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	17	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	17	MISC LABOUR CODE (EXTERNAL)		0.33	185.00	61.05
Z990	17	MISC LABOUR CODE (EXTERNAL)		0.17	185.00	31.45
Z990	17	MISC LABOUR CODE (EXTERNAL)		1.50	185.00	277.50
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	11	MISC LABOUR CODE (EXTERNAL)		0.25	185.00	46.25
Z990	12	MISC LABOUR CODE (EXTERNAL)		0.25	185.00	46.25
Z990	15	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	19	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	19	MISC LABOUR CODE (EXTERNAL)		1.00	185.00	185.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	4	UPS-CONSOLE		1.00	11.07	11.07
FRT	6	FED-EX - JOBS 6,10,14,16		1.00	41.52	41.52
FRT	17	UPS-PRESSED BOARD		1.00	12.53	12.53
SS	1	SHOP SUPPLIES		1.00	0.00	0.00

Parts Total: 353.10
 Labour Total: 1,535.50
 Sublet Total: 0.00
 Extras Total: 65.12

>>>> Claim Total: 1,953.72

Customer Signature: _____

Date: _____