

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 2446567 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 4X4TCKE29TK097079 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 094 / 094A ITEM # CKT29NM-94 DEALER RO # 77832 CLAIM START DATE 09/24/2025 CLAIM END DATE 01/01/1900
Labor rate: \$185.00 OWNER INFORMATION	
Retail Date of Purchase	WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	Operational Description		
20-44-19-00-000553	Roof Moldings - Front or Rear - Exterior/Roof/Reseal/No Tread Code		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2025-09-24 13:10:37 :: MANY VOIDS ON THE ROOF Voids on roof During pdi noticed voids in dicor on roof as well as cracking in dicor around solar conection filled voids with dicor.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
Notes			

Labor

Line# 2

Operation Code	Operational Description		
20-43-19-00-004330	Spot Seal Exterior (Dealer) - Exterior/Exterior Miscellaneous/Reseal/No Tread Code		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2025-09-24 13:11:05 :: VOIDS AROUND THE SIDE OF THE UNIT Multiple voids in unit exterior During pdi noticed mutple voids are seals on exterior of unit. Ran clear silicone to seal voids			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt \$37.00
Notes			

Labor

Line# 3

Operation Code	Operational Description		
60-136-15-00-001499	Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2025-09-24 13:11:58 :: OUTSIDE SHOWER LEAKS Outside shower leaking. Outside shower was leaking. Checked connections and they were lose at hot and cold and shower. Tightned all three and shower stopped leaking			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt \$18.50
Notes			
thank you			

Labor

Line# 4

Operation Code	Operational Description		
20-66-02-17-000672	Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch		
Complaint, Cause, Correction			
Original Note : bhoffman@americanrvcenter.com, 2025-09-24 13:12:22 :: BATHROOM DOOR DOESNT LATCH Bathroom door will not latch During pdi noticed bathroom door was not latching. Too, screws out and pulled			

latch as far forward as possible. Door latch now.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00

Notes

**Labor
Line# 5**

Operation Code	Operational Description
20-66-01-00-000658	Entry Door - Exterior/Entry Doors/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-09-24 13:12:43 :: THE FRONT DOOR HAS A SCRATCH ON IT Front door has scratch During pdi noticed front entry door has scratch on it. Parts request put in

Additional Note : bhoffman@americanrvcenter.com, 2025-09-24 13:13:01 :: ENTRY DOOR HAS A DECAL

Model#	Dlr Sub Hrs	1.60	Sub Labor Amt	\$296.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00

Notes

where is your completed, signed and dated DAF? ***PER THE DAF GUIDELINES, DEALERS SHOULD ATTACH ALL COMPLETED, SIGNED AND DATED DAFS TO THE VIN FILE WITHIN 3 DAYS OF DELIVERY***

thank you

done thank you

changed to repair code

thank you please use a Magic Eraser on the scratch

update Part only for entry door

Forest River authorized dealer part only, Forest River has no documentation on the issue when dealer received the unit.

Dealer authorized .20 for trying to clean off door

thank you

Submitted	Labor Amt	\$425.50	Approved	Labor Amt	\$166.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$425.50		Total	\$166.50

DEALER **DATE**
SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**
SIGNATURE

All repairs described have been inspected and are satisfactory.