

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77834
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11650 - 2026 SPRINGDALE 291BRC 4YDTSGP26T7100538

VIN: 4YDTSGP26T7100538 HIN: SER#: 4YDTSGP26T7100538

Mileage: 0

Work Order Comp: 23 OCT 25

Auth. No:

Dealer #: 1194

Warr. Date:

Work Order Date: 17 SEP 25

Inv #: 423568

WO # Job # Description JOB INFORMATION

77834 1 LP TANK WILL NOT FILL
 Lp tank wont fill.
 During pdi noticed lp tank wouldnt fill. Tried adjusting tank to
 allow for flow to fill and could not. Replaced tank.

77834 3 HOLE IN THE BLIND VALANCE ABOVE COUCH
 Holes in fabric above couch blinds
 During pdi noticed that the fabric on the blind cover had a hole
 on both sides where a screw was put and then removed.

77834 4 DENTS AND SCRATCHS ON FRIDGE AND FREEZER DOOR
 Dents in fridge doors
 During pdi noticed thatthe freezer door had a dent and fridge
 door had scratches on it

77834 5 BUNK ROOM COUNTER TOP DAMAGED
 Bunk room countertop damaged
 During pdi noticed that the counter top in the bunkroom had to
 gouges taken out of it

77834 6 UNIT WAS BUILD WITH A FURRION AND A DOMETIC A/C PER KEYSTONE IT
 SHOULD BE DOMETIC
 Wrong ac unit
 During pdi noticed that the rear ac unit was dometic and front
 ac unit was a furrion. Took multiple pictures of ac unit on
 camper. Parts requested for dometic unit

Claim : 77834

 WO # Job # Description JOB INFORMATION

77834 2 ENTRY DOOR NEEDS ADJUSTED
 Adjust entry door
 During pdi noticed entry door would not latch properly. Check
 hinges to be good. Adjusted striker plate. Door shuts better

 Part No Job# Description PARTS Qty Price Total

 FLKYSN201 1 L.P.CYLINDER 20 LB. PW 1.00 72.24 72.24
 769052 3 LARGE WINDOW VALANCE - KEYSTONE W 1.00 23.02 23.02
 672546 4 Refrigerator - Refrigerator Door 1.00 684.68 684.68
 672545 4 Freezer Door - Black - Fits - GPV 1.00 380.73 380.73
 11975 5 DRESSERTOP-"13 X 42"SG 1.00 8.02 8.02
 DOMFJX3473MWH 6 13.5 FRESHJET AIR CONDITIONER 1.00 841.69 841.69
 DOM3314851.00 6 CEILING KIT - BRISK AIR - POLAR W 1.00 179.10 179.10

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 1 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 3 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 3 MISCELLANEOUS REPAIR 0.04 180.00 7.20
 Z990 3 MISCELLANEOUS REPAIR 0.06 180.00 10.80
 Z990 4 MISCELLANEOUS REPAIR 0.44 180.00 79.20
 Z990 4 MISCELLANEOUS REPAIR 0.04 180.00 7.20
 Z990 4 MISCELLANEOUS REPAIR 0.52 180.00 93.60
 Z990 5 MISCELLANEOUS REPAIR 1.00 180.00 180.00
 Z990 5 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 5 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 6 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 6 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 6 MISCELLANEOUS REPAIR 0.40 180.00 72.00
 Z990 6 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 6 MISCELLANEOUS REPAIR 0.80 180.00 144.00
 Z990 2 MISCELLANEOUS REPAIR 0.20 180.00 36.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 3 FREIGHT 1.00 41.61 41.61
 FRT 4 UPS-REFER DOOR 1.00 88.10 88.10
 FRT 5 UPS-DRESSER TOP 1.00 41.61 41.61

Parts Total: 2,189.48
 Labour Total: 738.00
 Sublet Total: 0.00
 Extras Total: 171.32

>>>> Claim Total: 3,098.80

Customer Signature: _____

Date: _____