



4:02:06 PM

Last Modified By

Original										Changed	
Reference		Repair			Repairing dealer			Labor	warranty	Date of	
Claim	no.	start date	Repair date	VIN	Pre-auth	Dealer	name	rate	rate	Type	Purchase
CLAIM32024 (C3875332)	77834	9/17/2025	10/23/2025	4YDTSGP26T7100538	PA03915317	1194	Basden's American RV 600 E Baseline Rd Evansville, IN 47725	180.00	0.00	WARR	1/1/1970
Deny	Item				Qty	Dealer	Part	Appr	Sub		
code	number	Name	Quantity	Returned	price	Markup	total	Freight	Freight	Sublet	Status
	345675	Bottle - LP - 20# - Dual Listed - CSA	1	1	72.24	30.00	93.91	0.00	0.00	0.00	Approved
7 7/30/25-within krv 25 Component Model 1											
93	769052		1	0	17.72	30.00	23.04	41.61	41.61	0.00	Approved
Dealer claimed 23.02 inv 5058059 shows cost at 17.72 Component Serial Number hole											
93	672546	Refrigerator - Refrigerator Door - Black - Fits - GPV10FGNBB-R & GPV10FGNBB-L	1	0	526.68	30.00	684.68	88.10	88.10	0.00	Approved
Dealer claimed 684.68 inv 5056116 shows cost at 526.68 Component Model 1 Component Serial Number scratch/dent											
93	672545	Refrigerator - Freezer Door - Black - Fits - GPV10FGNBB-R & GPV10FGNBB-L	1	0	292.87	30.00	380.73	0.00	0.00	0.00	Approved
Dealer claimed 380.73 inv 5056116 shows cost at 292.87 Component Model 1 Component Serial Number scratch/dent											
93	721310	DresserTop-13" x 42" SG	1	0	6.17	30.00	8.02	41.61	41.61	0.00	Approved
Dealer claimed 8.02 inv 5059956 shows cost at 6.17 Component Serial Number scuffed/chipped											
99	699762	A/C - 5K BTU - GE - Room Air Conditioner - 12 9/16" x 16 7/16" x 15"	1	0	425.12	30.00	552.66	70.00	0.00	0.00	Approved
Paid krv cost 25 30 mu/freight Component Model 1 Component Serial Number Incorrect AC in unit											
99	410460	A/C - Ceiling Assembly Kit - Advent Air - w/Thermostat - Flash Cool	1	0	78.50	30.00	102.05	20.00	0.00	0.00	Approved
Paid krv cost 25 30 mu/freight Component Model 1 Component Serial Number Incorrect AC in unit											
14	699762	A/C - 5K BTU - GE - Room Air Conditioner - 12 9/16" x 16 7/16" x 15"	1	0	501.54	0.00	501.54	0.00	0.00	0.00	Denied
Dealer claimed 841.69/1094.20 over KRV cost Component Serial Number x											
14	410460	A/C - Ceiling Assembly Kit - Advent Air - w/Thermostat - Flash Cool	1	0	110.78	0.00	110.78	0.00	0.00	0.00	Denied
Dealer claimed 179.10/232.83 over KRV cost Component Serial Number x											
Deny code	Operation	Description	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status		
	6200208B	LP Bottle - Replace	0.2	0.2	36	0	1	0.2	Approved		
	Complaint LP TANK WILL NOT FILL				Notes Stock						
	Cause Lp tank wont fill.				36						
	Correction During pdi noticed lp tank wouldnt fill. Tried adjusting tank to allow for flow to fill and could not. Replaced tank.										
	KRV — Labor time approved in accordance with Keystone RV’s flat rate manual.										
	VCB: Vendor Charge Back item										

Claim CLAIM32024 (C3875332)

Last Modified By

Submitted parts & subLet		2,457.41	Approved parts & subLet		1,845.09
Submitted labor & subLet		738.00	Approved labor & subLet		738.00
Submitted freight		171.32	Approved freight		261.32
Total Submitted		<u>3,366.73</u>	Total approved		<u>2,844.41</u>