



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77834



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 77834

Customer: 1000 - BASDEN'S AMERICAN

RV -

Tag:

Author: PH

Location: 1021 BH TO CLOSE

Stock #: 11650

Stock Desc: 2026 TT KEYSTONE

SPRINGDALE 291BRC

Chassis #: 4YDTSGP26T7100538

Serial #: 4YDTSGP26T7100538

Mileage: 0

Licence:

Invoice #:

Date In: 17 SEP 25

Promised:

Date Sched:

Completed: 23 OCT 25

Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*77929 on 30 SEP 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: LP TANK WILL NOT FILL

CAUSE: Lp tank wont fill.

CORRECTION: During pdi noticed lp tank wouldnt fill. Tried adjusting tank to allow for flow to fill and could not. Replaced tank.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	36.00
Z990	MISCELLANEOUS REPAIR	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
66-4905	L.P.CYLINDER 20 LB. PW	1.00	72.24	72.24

Subtotal for Job #1: 108.24

Job #2 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED



CAUSE: Adjust entry door

CORRECTION: During pdi noticed entry door would not latch properly. Check hinges to be good. Adjusted striker plate. Door shuts better

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	36.00
Subtotal for Job #2:			36.00

Job #3 - Warranty

COMPLAINT: HOLE IN THE BLIND VALANCE ABOVE COUCH

CAUSE: Holes in fabric above couch blinds

CORRECTION: During pdi noticed that the fabric on the blind cover had a hole on both sides where a screw was put and then removed.

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	18.00
Z990	MISCELLANEOUS REPAIR	CCV	7.20
Z990	MISCELLANEOUS REPAIR	CCV	10.80

Parts				
Part #	Description	Qty	Price	Total
769052	LARGE WINDOW VALANCE - KEYSTONE WOOD	1.00	23.02	23.02

Other Services				
Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	41.61	41.61
Subtotal for Job #3:				100.63

Job #4 - Warranty

COMPLAINT: DENTS AND SCRATCHS ON FRIDGE AND FREEZER DOOR

CAUSE: Dents in fridge doors

CORRECTION: During pdi noticed that the freezer door had a dent and fridge door had scratches on it

Labor			
Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	79.20
Z990	MISCELLANEOUS REPAIR	CCV	7.20
Z990	MISCELLANEOUS REPAIR	CCV	93.60

Parts				
Part #	Description	Qty	Price	Total
672546	Refrigerator - Refrigerator Door - B	1.00	684.68	684.68
672545	Freezer Door - Black - Fits - GPV10F	1.00	380.73	380.73

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-REFER DOOR	1.00	88.10	88.10
Subtotal for Job #4:				1,333.51

Job #5 - Warranty

COMPLAINT: BUNK ROOM COUNTER TOP DAMAGED

CAUSE: Bunk room countertop damaged



Customer #: 1000
BASDEN'S AMERICAN RV,



CORRECTION: During pdi noticed that the counter top in the bunkroom had to gouges taken out of it

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	180.00
Z990	MISCELLANEOUS REPAIR	CCV	0.00
Z990	MISCELLANEOUS REPAIR	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
11975	DRESSERTOP-"13 X 42"SG	1.00	8.02	8.02

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DRESSER TOP	1.00	41.61	41.61

Subtotal for Job #5: 229.63

Job #6 - Warranty

COMPLAINT: UNIT WAS BUILD WITH A FURRIION AND A DOMETIC A/C PER KEYSTONE IT SHOULD BE DOMETIC

CAUSE: Wrong ac unit

CORRECTION: During pdi noticed that the rear ac unit was dometic and front ac unit was a furrion. Took multiple pictures of ac unit on camper. Parts requested for dometic unit

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	CCV	0.00
Z990	MISCELLANEOUS REPAIR	CCV	36.00
Z990	MISCELLANEOUS REPAIR	CCV	72.00
Z990	MISCELLANEOUS REPAIR	CCV	18.00
Z990	MISCELLANEOUS REPAIR	CCV	144.00

Parts

Part #	Description	Qty	Price	Total
2790	13.5 FRESHJET AIR CONDITIONER	1.00	841.69	841.69
2791	CEILING KIT - BRISK AIR - POLAR WHIT	1.00	179.10	179.10

Subtotal for Job #6: 1,290.79

Parts Total: 2,189.48
 Labour Total: 738.00
 Sublet Total: 0.00
 Extras Total: 171.32
WORK ORDER TOTAL: 3,098.80

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Oct 2025



Customer #: 1000
 BASDEN'S AMERICAN RV,

