

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
 CLAIM 2447940
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 4X4TCKE21TK097013
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 094 / 094A
 ITEM # CKT29NM-94
 DEALER RO # 77835
 CLAIM START DATE 09/25/2025
 CLAIM END DATE 01/01/1900

Labor rate: \$185.00
 OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 20-46-24-00-000721 Window - Exterior/Windows/Repair/No Tread Code
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-09-25 12:21:11 :: BACK WINDOW SEAL NEEDS TO BE FIXED Rear window seal tucked. Got the the tuck out and massaged the seal and made sure it was in there correctly. All good now
 Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$37.00
 Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$37.00
 Notes

Labor

Line# 2 **Operation Code** **Operational Description**
 20-66-02-17-000672 Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch
Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-09-25 12:22:30 :: INTERIOR BEDROOM DOOR NEEDS STRIKER ADJUSTED. WILL NOT LATCH. Rear bedroom entry door needed adjusted I adjusted the striker plate on the door frame a little. And the door shuts properly now
 Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$37.00
 Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$37.00
 Notes

Submitted Labor Amt \$74.00
 Parts & Freight \$0.00
 Total \$74.00

Approved Labor Amt \$74.00
 Parts & Freight \$0.00
 Total \$74.00

DEALER _____ DATE _____
 SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
 SIGNATURE

All repairs described have been inspected and are satisfactory.