



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77835

CUSTOMER WORK ORDER

WO #: 77835

Customer: 1000 - BASDENS AMERICAN
RV -
Tag:
Author: BH
Location: 1015 CHECK PREAUTH

Stock #: 11652
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE GREY WOLF 29NM
Chassis #: 4X4TCKE21TK097013
Serial #: 4X4TCKE21TK097013
Mileage: 0
Licence:

Invoice #:
Date In: 17 SEP 25
Promised:
Date Sched:
Completed: 26 SEP 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery box. Filled 2 20# lp tanks and turned the regulator facing the camper. Exterior inspection bedroom exterior entry door hits hard on striker. Main door hits hard on striker. Back window seal tucked. Roof inspection found some voids in the sealer that I filled with dicor self-leveling roof good now. Off door side front corner ther was a void in the black dicor so i filled with dicor looks good now. Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly outside refrigerator works properly water heater works properly. All the lights work properly all outlets work properly and USB ports all windows and blinds work properly. Put water in fresh tank and ran the water pump there was a rattle sound when put ran. Looked into it and the factory left a piece of metal laying by the pump. I removed it and pump sounds better now and works properly. Flushed out all the lines with the water pump. Did my lp drop test on outside port with stove and water heater running no adjustment needed to the regulator. System works properly. All the cabinets work properly. Tv antenna works properly. Drained black and gray tanks and fresh water tank. And put company logo stickers on unit

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Internal

COMPLAINT: BDROOM OUTSIDE DOOR HITS THE STRIKER

CAUSE: Door was hitting hard on the striker plate

CORRECTION: I adjusted the hing side of the door so it wouldn't hit so hard on the striker plate. Door shuts



Customer #: 1000
BASDENS AMERICAN RV,



properly now

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Subtotal for Job #1:			0.00

Job #2 - Internal

COMPLAINT: MAIN DOOR HITS HARD ON THE STRIKER

CAUSE: Door hitting hard on door striker

CORRECTION: After inspection of the door found that the screen door was hitting on the hindge side of the frame. I got that fixed and it shuts properly now. And then the main door the striker plate was too low so i fixed that then i adjusted the door at the hinges to give it clearance at the striker plate. Door shuts properly now

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Subtotal for Job #2:			0.00

Job #3 - Warranty

COMPLAINT: BACK WINDOW SEAL NEEDS TO BE FIXED

CAUSE: Rear window seal tucked.

CORRECTION: Got the the tuck out and massaged the seal and made sure it was in there correctly. All good now

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00
Subtotal for Job #3:			37.00

Job #4 - Warranty

COMPLAINT: INTERIOR BEDROOM DOOR NEEDS STRIKER ADJUSTED. WILL NOT LATCH.

CAUSE: Rear bedroom entry door needed adjusted

CORRECTION: I adjusted the striker plate on the door frame a little. And the door shuts properly now

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00
Subtotal for Job #4:			37.00

Parts Total:	0.00
Labour Total:	74.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	74.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 77835



Customer #: 1000
BASDEN'S AMERICAN RV,

