



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77836
Promised Date:
24 OCT 25

CUSTOMER WORK ORDER

WO #: 77836

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 1021 BH TO CLOSE

Stock #: 11648
Stock Desc: 2026 5W KEYSTONE
COUGAR HALF-TON 29BHL
Chassis #: 4YDFCGN26T2500867
Serial #: 4YDFCGN26T2500867
Mileage: 0
Licence:

Invoice #:
Date In: 17 SEP 25
Promised: 31 OCT 25
Date Sched:
Completed: 23 OCT 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*77979 on 07 OCT 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: Checked appliances, brakes, tire pressure, torqued lugs, checked electrical system, and plumbing system checked cabinets doors and drawers. Filled l.p tanks and ran l.p drop test. Checked roof

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: UNIT HAS WHAT APPEARS TO BE 2 SETS OF LOW POINT DRAINS AND ONE SET HAS NO SHUT OFFS.

CAUSE: When running the city water and fresh tank pump, i noticed there are a set of low point drain that dont have valeves on them. When i try to run water through the water system, it comes out these 2 lines.

CORRECTION: Recieved 2 shut-off valves from parts. Crimped both fittings on hot and lines. Pressurized water system. The water system is now working properly.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	72.00

Parts

Part #	Description	Qty	Price	Total
30879	30879 Shut Off Valve; PEXLock; Stop	2.00	6.67	13.34

Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 77836
Promised Date: 31 OCT 25



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 85.34

Job #2 - Warranty

COMPLAINT: BACK SPLASH LOOSE

CAUSE: Backsplash is loose from the wall

CORRECTION: Applied spray adhesive to the wall and secured the backsplash.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	18.00

Subtotal for Job #2: 18.00

Job #3 - Warranty

COMPLAINT: THE LINO NEAR THE DINNETTE IS DAMAGED AND NEEDS FIXED

CAUSE: Linolium

CORRECTION: Went to the house to find a piece of linolium to go under the cabinets. Cut out linolium under sink. Glue new piece down. Layed out and taped off replacement piece. Cut out and glued down.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	ZMS	10.80
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	7.20
Z990	MISCELLANEOUS REPAIR	BB	72.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	126.00

Parts

Part #	Description	Qty	Price	Total
767089	S/O-LINO	1.00	74.40	74.40

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LINO	1.00	12.00	12.00

Subtotal for Job #3: 302.40

Parts Total:	87.74
Labour Total:	306.00
Sublet Total:	0.00
Extras Total:	12.00
WORK ORDER TOTAL:	405.74

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Oct 2025





600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77836
Promised Date:
24 OCT 25

CUSTOMER WORK ORDER

WO #: 77836

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 1021 BH TO CLOSE

Stock #: 11648
Stock Desc: 2026 5W KEYSTONE
COUGAR HALF-TON 29BHL
Chassis #: 4YDFCGN26T2500867
Serial #: 4YDFCGN26T2500867
Mileage: 0
Licence:

Invoice #:
Date In: 17 SEP 25
Promised: 31 OCT 25
Date Sched:
Completed: 23 OCT 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*77979 on 07 OCT 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: Checked appliances, brakes, tire pressure, torqued lugs, checked electrical system, and plumbing system checked cabinets doors and drawers. Filled l.p tanks and ran l.p drop test. Checked roof

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: UNIT HAS WHAT APPEARS TO BE 2 SETS OF LOW POINT DRAINS AND ONE SET HAS NO SHUT OFFS.

CAUSE: When running the city water and fresh tank pump, i noticed there are a set of low point drain that dont have valeves on them. When i try to run water through the water system, it comes out these 2 lines.

CORRECTION: Recieved 2 shut-off valves from parts. Crimped both fittings on hot and lines. Pressurized water system. The water system is now working properly.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	72.00

Parts

Part #	Description	Qty	Price	Total
30879	30879 Shut Off Valve; PEXLock; Stop	2.00	6.67	13.34



Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 77836
Promised Date: 31 OCT 25



Customer #: 1000
BASDENS AMERICAN RV,



Subtotal for Job #1: 85.34

Job #2 - Warranty

COMPLAINT: BACK SPLASH LOOSE

CAUSE: Backsplash is loose from the wall

CORRECTION: Applied spray adhesive to the wall and secured the backsplash.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	18.00

Subtotal for Job #2: 18.00

Job #3 - Warranty

COMPLAINT: THE LINO NEAR THE DINNETTE IS DAMAGED AND NEEDS FIXED

CAUSE: Linolium

CORRECTION: Went to the house to find a piece of linolium to go under the cabinets. Cut out linolium under sink. Glue new piece down. Layed out and taped off replacement piece. Cut out and glued down.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	ZMS	10.80
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	7.20
Z990	MISCELLANEOUS REPAIR	BB	72.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	126.00

Parts

Part #	Description	Qty	Price	Total
767089	S/O-LINO	1.00	74.40	74.40

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-LINO	1.00	12.00	12.00

Subtotal for Job #3: 302.40

Parts Total:	87.74
Labour Total:	306.00
Sublet Total:	0.00
Extras Total:	12.00
WORK ORDER TOTAL:	405.74

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Oct 2025

