

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2450139
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAVBXTX035655
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	205 / 205
Labor rate:	\$185.00	ITEM #	ACAT303RKDSLE
OWNER INFORMATION		DEALER RO #	77837
		CLAIM START DATE	09/27/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 20-69-02-00-000705	Operational Description Compartment Door - Exterior/Compartment Doors/Adjust/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-09-27 13:16:50 :: COMPARTMENT DOOR IS HITTING THE FRAME Side compartment door hitting in the corner Adjusted the frame so the door wouldn't hit the door. Door shuts properly now			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			

Labor

Line# 2	Operation Code 10-7-15-16-000144	Operational Description Entry Step - Weld - Frame & Chassis/Manual Entry Step/Repair or Replace/Structure		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-09-27 13:28:49 :: ENTRY STEPS NEED ADJUSTED, HITTING DOOR FRAME Door hitting stairs Adjusted the door and is not hitting the stairs anymore			
Model#	Dlr Sub Hrs	0.25	Sub Labor Amt	\$46.25
Serial#	Appr Hrs	0.25	Appr Labor Amt	\$46.25
	Notes			

Labor

Line# 3	Operation Code 30-101-24-00-001079	Operational Description Sliding, Pocket Door Track - Interior/Interior Doors/Repair/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-09-27 13:37:52 :: CLOSET DOOR CEILING TRACK HAS RIPPED OUT OF THE CEILING AND NEEDS TO BE RE-INSTALLED BH TALKED TO JOHN ABOUT THE SLIDING DOOR INSTALL AND THE RAIL FALLING Door track come out of the ceiling So i took track off and found there wasn't any support in the ceiling. So i had to use toggle bolts to secure track to ceiling. Door work properly now. Had to put stops in track so the door wouldn't come off track. Good to go now			
Model#	Dlr Sub Hrs	2.00	Sub Labor Amt	\$370.00
Serial#	Appr Hrs	2.00	Appr Labor Amt	\$370.00
	Notes AUTHORIZED AS REQUESTED			

Labor

Line# 4	Operation Code 30-102-12-00-001096	Operational Description Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code	
	Complaint, Cause, Correction		

Original Note : bhoffman@americanrvcenter.com, 2025-09-27 13:40:50 :: INTERIOR TRIM AROUND THE ENTRY DOOR HAS COME COMPLETELY LOOSE AND NEEDS TO HAVE THE STAPLES REMOVED AND TRIM STAPLED BACK TO THE WALL AND STAPLE MARKS FILLED WITH PUTTY Door trim coming off Took piese off removed the stapels and then i re stapled it and filled the holes. And then the other side was loose and i shot some stapels in it and filled them

Model# Dlr Sub Hrs 0.10 Sub Labor Amt \$18.50
Serial# Appr Hrs 0.10 Appr Labor Amt \$18.50

Notes

Labor

Line# 5 Operation Code Operational Description
60-136-01-00-001480 City Water Connection - Plumbing/Fresh Water Supply/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-09-27 13:41:22 :: CITY WATER INLET CONNECTION IS BROKEN City water inlet broke off Removed the rest of the city water inlet and replaced it with a new one. Work properly now

Model# Dlr Sub Hrs 0.30 Sub Labor Amt \$55.50
Serial# Appr Hrs 0.30 Appr Labor Amt \$55.50

Notes

Submitted	Labor Amt	\$527.25	Approved	Labor Amt	\$527.25
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$527.25		Total	\$527.25

DEALER DATE
SIGNATURE
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER DATE
SIGNATURE
All repairs described have been inspected and are satisfactory.