



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77837



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 77837

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 1001 CHECK PREAUTH

Stock #: 11654
Stock Desc: 2026 TT COACHMEN
CATALINA 303RKDSLE
Chassis #: 5ZT2CAVBXTX035655
Serial #: 5ZT2CAVBXTX035655
Mileage: 0
Licence:

Invoice #:
Date In: 17 SEP 25
Promised:
Date Sched:
Completed: 29 SEP 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Running lights and tail lights work properly brakes and Emergency Brakes work properly. Installed a battery box. Self-leveling system works properly. Exterior inspection had to adjust the screen door and the main entry door. Door works properly now fixed the door side fender. Had to calibrate the self leveling system because it was off. Exterior inspection looks good now. Roof inspection one some void in the sealer that I filled with dicor self-leveling. Roof good now. Interior inspection hooked up to city water and flushed out all the lines. Water heater works properly now it had a blown fuse on the unit itself. Stove works properly microwave works properly refrigerator works properly ac works properly furnace works properly all windows and blinds work properly all outlets work properly and USB ports work properly. Put water in fresh tank and ran the water pump and it worked properly. Drined the black and gray tanks and Drined the fresh tank. Fixed the trim on both sides of entry dood. Have to fix the slider closet door pulled out of the ceiling. Got the door track secured to ceiling and had to put door stop so the rollers don't come out of the track. Door works properly now

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: COMPARTMENT DOOR IS HITTING THE FRAME

CAUSE: Side compartment door hitting in the corner

CORRECTION: Adjusted the frame so the door wouldn't hit the door. Door shuts properly now



Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00
Subtotal for Job #1:			37.00

Job #3 - Warranty

COMPLAINT: ENTRY STEPS NEED ADJUSTED, HITTING DOOR FRAME

CAUSE: Door hitting stairs

CORRECTION: Adjusted the door and is not hitting the stairs anymore

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	3.70
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	42.55
Subtotal for Job #3:			46.25

Job #4 - Warranty

COMPLAINT: CLOSET DOOR CEILING TRACK HAS RIPPED OUT OF THE CEILING AND NEEDS TO BE RE-INSTALLED

CAUSE: BH TALKED TO JOHN ABOUT THE SLIDING DOOR INSTALL AND THE RAIL FALLING
Door track come out of the ceiling

CORRECTION: So i took track off and found there wasn't any support in the ceiling. So i had to use toggle bolts to secure track to ceiling. Door work properly now. Had to put stops in track so the door wouldn't come off track. Good to go now

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	277.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts				
Part #	Description	Qty	Price	Total
H750	H750 18" CLEAR PLASTIC TIEBACK	1.00	6.64	6.64
H528	H528 1-SET SLIDING DOOR GUIDE	1.00	5.36	5.36
Subtotal for Job #4:				382.00

Job #5 - Warranty

COMPLAINT: INTERIOR TRIM AROUND THE ENTRY DOOR HAS COME COMPLETELY LOOSE AND NEEDS TO HAVE THE STAPLES REMOVED AND TRIM STAPLED BACK TO THE WALL AND STAPLE MARKS FILLED WITH PUTTY

CAUSE: Door trim coming off

CORRECTION: Took piece off removed the staples and then i re stapled it and filled the holes. And then the other side was loose and i shot some staples in it and filled them

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50
Subtotal for Job #5:			18.50

Job #2 - Warranty

COMPLAINT: CITY WATER INLET CONNECTION IS BROKEN

CAUSE: City water inlet broke off

Customer #: 1000
BASDEN'S AMERICAN RV,

CORRECTION: Removed the rest of the city water inlet and replaced it with a new one. Work properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Parts

Part #	Description	Qty	Price	Total
10-1105	62165 PW METAL MPT CITY WATER FLANGE	1.00	16.32	16.32

Subtotal for Job #2: 71.82

Job #6 - Internal

COMPLAINT: NO POWER TO THE WATER HEATER

CAUSE: No power to water heater

CORRECTION: Checked everything and it came down to a blown fuse outside on the water heater it self. I replaced the fuse and it works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Subtotal for Job #6: 0.00

Parts Total: 28.32
Labour Total: 527.25
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 555.57

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 29 Sep 2025

W/O: 77837



Customer #: 1000
BASDEN'S AMERICAN RV,

