



Warranty Authorization Form

Date: 11/13/2025

General Information

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

Pre-Auth #: 105778

Unit: 7M5FP4323RB203763

Series: Paradigm

Model: 2024PAR395DS

Notes: 9/25: Dayra - Vendor approved – “I can send out a new handle at no charge. I can also offer up to .25 hrs. in labor credit for the repair.” - part will be sent direct – attached 9/23: Dayra - Sent to the Vendor awaiting response.

Status: Approved with Modifications

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 22672 SHOWER DOOR - HANDLE - REPLACE (VENDOR AUTH REQUIRED -Vendor can send parts direct)(Photos Required) *Fault Code:* VENDOR

Serial #: *Model #:* *Notes:* 9/25: Dayra - Vendor approved – “I can send out a new handle at no charge. I can also offer up to .25 hrs. in labor credit for the repair.” - part will be sent direct – attached 9/23: Dayra - Sent to the Vendor awaiting response.

Problem: SHOWER LATCHES ARE STRIPPED AND FALLING APART

Time Requested: .25

Cause: FOUND HANDLE BROKEN AND NEEDS REPLACED

Time Allowed: .25

Remedy: REPLACE SHOWER HANDLE

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved