

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77876
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11641 - 2026 CHEROKEE WOLF PUP 16CM 5ZT2CKEC6TY039081
VIN: 5ZT2CKEC6TY039081 HIN: SER#: 5ZT2CKEC6TY039081
Mileage: 0 Work Order Comp: 24 OCT 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 23 SEP 25 Inv #: 423632

WO # Job # Description JOB INFORMATION

77876 2 THE ENTRY DOOR SEAL IS NOT INSTALLED CORRECTLY
Seal incorrectly installed and pinched in frame when shut.
Door seal was not correctly installed and is being pinched
between the door and jam when closed. Permanent mark is left on
seal and needs replaced. 166 in of seal is needed to replace.
Received new seal from parts and installed it. To install like
manufacture i had to pull the door hinges.

77876 1 THE OUT DOOR WATER ARE IS WARRPED
Corners of water connection are warped and folding.
Received new Water Connection hookup. Removed old one and
disconnected the City and Fresh Tank fill hoses. Cleaned the
majority of old sealant. Installed Puddy around edges of new
Hookup. Hooked up city and fill connections to new Hookup.
Installed with new screws and added 2 more screws to top corners
and sealed around with Clear Sealant.

77876 6 THE DECAL ON THE DOOR IS TORN
Decal has small tear.
Decal has small damages.

77876 3 THE OUTSIDE FRIDGE METAL TIN IS IN ROUGH SHAPE
Unmounted and removed Outside Fridge from compartment and sprayed
down Water marks on Metal with Mineral Spirits and scrubbed them
down. Most the White surface grim came off but left tarnish in
the metal itself.

Claim : 77876

 WO # Job # Description JOB INFORMATION

77876 4 ENTRY DOOR IS RUBBING THE FRAME, NEEDS ADJUSTED
 Entry door is rubbing frame.
 Pulled screw that holds the little gutter thing and used a block
 of wood and attempted to hammer over the area rubbing but there
 is no give to the area and solid on the backside so im assuming
 the door and frame would have to be removed to either cut back
 the metal or the wooded frame. Inside the door frame measuring 25
 3/8 at bottom, 25 3/8 in the middle, and 25 1/4 at the top.
 Advised Ben on this.

Part No	Job#	Description	PARTS	Qty	Price	Total
321161	2	Seal - D Seal - EPDM - .57" x .4		14.00	0.42	5.88
94223	1	CITY/GRAVITY DISH, PLASTIC CHECK		1.00	19.36	19.36
F100616132	6	DECAL, 2025/2026 CHEROKEE DOOR LE		1.00	10.40	10.40
12009	3	FLT BLACK SPRAY PAINT		2.00	6.49	12.98

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	6	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00

Excode	Job#	Description	EXTRAS	Qty	Price	Total
FRT	6	UPS-DECAL		1.00	15.85	15.85

Parts Total: 48.62
 Labour Total: 314.50
 Sublet Total: 0.00
 Extras Total: 15.85

>>>> Claim Total: 378.97

Customer Signature: _____

Date: _____