

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77887
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 56259 - BRANDON NEBER
Address: 1822 KEYSTONE DR PRINCETON, IN

47670

Phone: 812-304-9030

Stock Number: 11665 - 2026 CATALINA 343BH7SLE 5ZT2CAZB8TX035809

VIN: 5ZT2CAZB8TX035809 HIN: SER#: 5ZT2CAZB8TX035809

Mileage: 0 Work Order Comp: 05 NOV 25

Auth. No: Dealer #:

Warr. Date: 09 OCT 25 Work Order Date: 24 SEP 25 Inv #: 424123

WO # Job # Description JOB INFORMATION

77887	1	Missing flapper in stove vent outside Flap for stove outside missing Found on my exterior inspection that the flapper was missing. Put in a parts request
77887	6	LP LINE TO THE OUSIDE GRILL TOO SHORT LP IS TOO SHORT REPLACE THE LINE
77887	7	CENTER CAP MISSING Center missing on Center cap On exterior inspection found that the center was missing from center cap. Put in a parts request
77887	2	USB IN THE RIGHT ABOVE THE SINK Usb port no power Took usb port out of cabinet no power coming in. So i traced the wire back to the connector and found out that it was a bad connection. Fixed it and i have power now. And it works properly now
77887	3	CO AND PROPANE GAS ALARM NOT WORKING Lp detector wont work Took lp detector off the wall. And found i had no power. Checked the fuse panel. Then took control panel off fou d the wire. No power traced to microwave took microwave out power there then we

Claim : 77887

 WO # Job # Description JOB INFORMATION

took the light out in between and found that the factory didn't strip the wire back far enough and it wasn't making contact. Stripped the wire back and put it back in the connector and everything works properly

77887 4 KITCHEN SINK DRAIN IS LEAKING
 Kitchen sink leaking
 Took connections apart to make sure the gaskets were i. Correct position and tightened all the connections and ran the water with no leaks. When i took it apart one connection was loose. Sink works properly now

77887 5 TRIM NEAR THE ENTRY DOOR IS LOOSE
 Trim loose
 Wall trim loose on latch side of door inside. I shot some staples in it and filled holes with putty.

 Part No Job# Description PARTS Qty Price Total

 C01237510 1 VENT, ENDURA RANGE VENT ASSY, 1-1 1.00 9.17 9.17
 11372 6 QC PROPANE HOSE KIT 0.00 45.86 0.00
 F100424284 7 CENTER CAP, 6 LUG 3.75 SS AMERICA 1.00 11.06 11.06

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.30 185.00 55.50
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.00 185.00 0.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.05 185.00 9.25
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.30 185.00 55.50
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.30 185.00 55.50
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.30 185.00 55.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS-VENT 1.00 15.85 15.85
 FRT 7 UPS-CENTER CAP 1.00 19.64 19.64

Parts Total: 20.23
 Labour Total: 286.75
 Sublet Total: 0.00
 Extras Total: 35.49

>>>> Claim Total: 342.47

Customer Signature: _____

Date: _____