




600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77887
Promised Date:
24 OCT 25



Customer #: 56259
NEBER, BRANDON



CUSTOMER WORK ORDER

WO #: 77887

Customer: 56259 - NEBER, BRANDON -
812-304-9030

Tag:

Author: PH

Location: 1110 CALL CUSTOMER

Stock #: 11665

Stock Desc: 2026 TT COACHMEN

CATALINA 343BHTSLE

Chassis #: 5ZT2CAZB8TX035809

Serial #: 5ZT2CAZB8TX035809

Mileage: 0

Licence:

Invoice #:

Date In: 24 SEP 25

Promised: 31 OCT 25

Date Sched:

Completed: 05 NOV 25

Warr. Date: 09 OCT 25

Job #PDINTT - Internal

COMPLAINT: Transferred to BAS*77980 on 07 OCT 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

CAUSE: New pdi

CORRECTION: Lug nuts torqued to spec air pressure correct in all 5 tires. Put in for a parts request for a missing center cap cover. Running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery box. Factory had the power jack wire running on top of lp tank tray. So i moved it so it ran under the lp tank tray. The 7 way wire wasn't in the loop bracket so i put it in it. Exterior inspection no flap in the hood vent on outside of camper found that both fenders need some sealer a couple of outside ports need some silicone on them. Rear slideroom has some scratches on one piece of metal. Took care of all the voids on exterior of camper. Roof inspection looks good. Interior inspection hooked up to city water and flushed out all the lines including washer hook ups. Stove works properly microwave works properly refrigerator inside and out works properly both ac work properly and furnace works properly all electrical outlets work properly. Smoke detector works properly co detector didn't work there was a loose connection i fixed that. All the usb ports work properly i did have to fix the one above the sink it had no power it works properly now. Kitchen sink leaked i fixed that. Radio works properly tv antenna works properly. Removed all the packing tape all the remotes work and are in cabinet above fireplace. Main door trim was coming off i fixed that. Did my lp drop test on outside port with stove and water heater running made a small adjustment to the regulator system works properly now water pump works properly drained the black tank and gray tanks and fresh tank. Fixed the curtain rod on back window. All windows and blinds work properly. Rear slideroom on the outside has 3 scuff marks the has gone through the paint that i put a parts request in for.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JTW	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: Missing flapper in stove vent outside





CAUSE: Flap for stove outside missing

CORRECTION: Found on my exterior inspection that the flapper was missing. Put in a parts request

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JRK	55.50
Parts				
Part #	Description	Qty	Price	Total
C01237510	VENT, ENDURA RANGE VENT ASSY, 1-1/2"	1.00	9.17	9.17
Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-VENT	1.00	15.85	15.85
Subtotal for Job #1:				80.52

Job #2 - Warranty

COMPLAINT: USB IN THE RIGHT ABOVE THE SINK

CAUSE: Usb port no power

CORRECTION: Took usb port out of cabinet no power coming in. So i traced the wire back to the connector and found out that it was a bad connection. Fixed it and i have power now. And it works properly now

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	55.50
Subtotal for Job #2:				55.50

Job #3 - Warranty

COMPLAINT: CO AND PROPANE GAS ALARM NOT WORKING

CAUSE: Lp detector wont work

CORRECTION: Took lp detector off the wall. And found i had no power. Checked the fuse panel. Then took control panel off fou d the wire. No power traced to microwave took microwave out power there then we took the light out in between and found that the factory didn't strip the wire back far enough and it wasn't making contact. Strippec the wire back and put it back in the connector and everything works properly

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	55.50
Subtotal for Job #3:				55.50

Job #4 - Warranty

COMPLAINT: KITCHEN SINK DRAIN IS LEAKING

CAUSE: Kitchen sink leaking

CORRECTION: Took connections apart to make sure the gaskets were i. Correct position and tightened all the connections and ran the water with no leaks. When i took it apart one connection was loose. Sink works properly now

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JTW	55.50
Subtotal for Job #4:				55.50

Job #5 - Warranty

COMPLAINT: TRIM NEAR THE ENTRY DOOR IS LOOSE





CAUSE: Trim loose

CORRECTION: Wall trim loose on latch side of door inside. I shot some stapels in it and filled holes with putty.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50
Subtotal for Job #5:			18.50

Job #6 - Warranty

COMPLAINT: LP LINE TO THE OUSIDE GRILL TOO SHORT

CAUSE: LP IS TOO SHORT

CORRECTION: REPLACE THE LINE

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Subtotal for Job #6:			37.00

Job #7 - Warranty

COMPLAINT: CENTER CAP MISSING

CAUSE: Center missing on
Center cap

CORRECTION: On exterior inspection found
that the center was missing from center
cap. Put in a parts request

Labor				
Code	Description		Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		JRK	9.25
Parts				
Part #	Description	Qty	Price	Total
F100424284	CENTER CAP, 6 LUG 3.75 SS AMERICAN C	1.00	11.06	11.06
Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-CENTER CAP	1.00	19.64	19.64
Subtotal for Job #7:				39.95

Job #8 - Internal

COMPLAINT: Transferred to BAS*78371 on 05 NOV 25

Estimate amount was 0.00

METAL IS DAMAGED ON THE REAR OFF DOOR SIDE OF THE CAMPER

CAUSE: One piece of metal paint rubbed off

CORRECTION: On exterior inspection found that one piece of metal on slideroom had 3 rub marks that is
through the paint. I put a parts request in

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C



Other Services

Code	Description	Qty	Price	Total
FRT	UPS-METAL	0.00	N/C	N/C

Subtotal for Job #8: 0.00

Parts Total: 20.23
Labour Total: 286.75
Sublet Total: 0.00
Extras Total: 35.49
WORK ORDER TOTAL: 342.47

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 05 Nov 2025

W/O: 77887
Promised Date: 31 OCT 25



Customer #: 56259
NEBER, BRANDON

