



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77911
Promised Date:
24 OCT 25

CUSTOMER WORK ORDER

WO #: 77911 (Appointment Date: 29 SEP 2025 - Time: 09:00am)

Customer: 56211 - WATTS, MICHEAL -

Tag:

Author: GA

Location: 1020 BH TO CLOSE

Stock #:

Stock Desc: 2022 5W ALLIANCE RV
PARADIGM

Chassis #:

Serial #: 7M5FP3420NB201553

Mileage:

Licence:

Invoice #:

Date In: 29 SEP 25

Promised: 31 OCT 25

Date Sched:

Completed: 21 OCT 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: SOLAR RECALL 23V701

CAUSE: Solar panel roof connection

CORRECTION: Went up on the roof with tools and supplies, then unscrewed the solar panel connection. Found the wires were already fixed to the recall. Took pictures of the connection. Screwed the solar panel connection back to the roof and covered it with Dicor.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	92.50

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 92.50

Job #2 - External

COMPLAINT: Transferred to BAS*78077 on 20 OCT 25

Estimate amount was 0.00

CUSTOMER WOULD LIKE TO HAVE DOOR SIDE SLIDROOM LOOKED AT. CUSTOMER THINKS IT MAY BE OUT OF ADJUSTMENT

CAUSE: Slideroom operation and sealing

CORRECTION: Ran out the doorside slideroom and checked to see if it was sealing on the bulb seals and checked with a tape measure. Couldn't find the doorside slideroom out of alignment.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Subtotal for Job #2: 0.00

Job #22E-055 - Warranty

COMPLAINT: RECALL FOR AWNING FABRIC

CAUSE: Front awning was ripped

CORRECTION: Opened the awning about a foot then ziptied the awning arms. Disconnected the power to the awning lights and pulled off the awning light strip from the awning fabric. Unscrewed the awning fabric from the gutter and the awning arms. Pulled off the awning tube with the awning fabric. Pulled the damaged



Customer #: 56211
WATTS, MICHEAL



fabric off the awning tube. Slid on the new awning fabric to the gutter and aligned then slid on the awning tube to the awning fabric. Set the awning tube on the awning arms and screwed in place. Closed up the awning and cut the zipties. Ran the awning out and aligned it again and closed the awning.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
8763	Solera Universal Vinyl Replacement F	1.00	N/C	N/C

Subtotal for Job #22E-055: 0.00

Parts Total: 0.00
 Labour Total: 92.50
 Sublet Total: 0.00
 Extras Total: 0.00

WORK ORDER TOTAL: 92.50


Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 21 Oct 2025

W/O: 77911
 Promised Date: 31 OCT 25



Customer #: 56211
 WATTS, MICHEAL

