

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2457755
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKB20TX167477
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT26SS
		DEALER RO #	77922
		CLAIM START DATE	10/04/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1

Operation Code	10-4-01-12-004683	Operational Description
Complaint, Cause, Correction		LED Light, Sealed - Frame & Chassis/12 Volt Exterior/Replace/Exterior Lighting
Original Note : bhoffman@americanrvcenter.com, 2025-10-04 14:40:49 :: OUTSIDE DUMP LIGHT IS NOT WORKING GOOD POWER AND GROUND NOT WORKING REPLACE THE LIGHT		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
Notes		

Labor

Line# 2

Operation Code	70-148-01-00-001701	Operational Description
Complaint, Cause, Correction		Speaker - Appliances/Radio/Replace/No Tread Code
Original Note : bhoffman@americanrvcenter.com, 2025-10-04 14:41:58 :: OUTSIDE SPEAKER HOUSEING IF BROKEN AND NEEDS REPLACED FOUND SPEAKER TIGHTENED TOO MUCH AND NEEDS REPLACED DUE TO DAMAGE INSTALL NEW SPEAKER		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
Notes		

Labor

Line# 3

Operation Code	20-46-24-00-000721	Operational Description
Complaint, Cause, Correction		Window - Exterior/Windows/Repair/No Tread Code
Original Note : bhoffman@americanrvcenter.com, 2025-10-04 14:43:44 :: FRONT WINDOW DOOR SIDE THE GASKET IS LOOSE AND COMING OUT Window seal tucked Ran my nylon flat stick in the seal and got the tuck out and seated the seal in its track. All good now		
Model#	Dlr Sub Hrs	Sub Labor Amt
	0.20	\$37.00
Serial#	Appr Hrs	Appr Labor Amt
	0.20	\$37.00
Notes		

Labor

Line# 4

Operation Code	40-197-01-11-001325	Operational Description
Complaint, Cause, Correction		30 or 50 Amp Shore Power Inlet - Electrical/110 Volt Exterior/Replace/Electrical
Original Note : bhoffman@americanrvcenter.com, 2025-10-04 14:44:23 :: THE LID FOR THE 30 AMP OUTLET WILL NOT STAY CLOSED Shore power outlet cover not stay shut Took outlet off camper and relieved the high spots that was not letting the outlet stay flat. Put budle behind outlet and used black silicone to seal up the side cover stays shut now. Good to go		

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50

Notes

Submitted	Labor Amt	\$166.50	Approved	Labor Amt	\$166.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$166.50		Total	\$166.50

DEALER _____ DATE _____
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
 All repairs described have been inspected and are satisfactory.