



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 77939



### CUSTOMER WORK ORDER

WO #: 77939 (Appointment Date: 02 OCT 2025 - Time: 10:00am)

Customer: 55939 - BREWER, KEVIN -  
812-454-4299

Tag:  
Author: GA

Location: 1003 CHECK STATUS WITH  
JW

Stock #:  
Stock Desc: 2021 TT FOREST RIVER  
SALEM  
Chassis #:  
Serial #: 4X4TSMZ23N7427362  
Mileage:  
Licence:

Invoice #: 422830  
Date In: 02 OCT 25  
Promised:  
Date Sched:  
Completed: 30 SEP 25  
Warr. Date:

#### Job #1 - External

COMPLAINT: CUSTOMER HAS A LEAK UNDER THE BATHROOM SINK THAT HE CAN'T FIND

CAUSE: Leake under bathroom sink

CORRECTION: After inspection of the water lines and sink drain. I noticed that all the conections were about 1/2 a turn loose. Including the drain conections. And the sink faucet nuts were about 2 turns loose. So i tightened up all the conections under the sink and hooked to city water and ran the faucet and didn't see a leak. Good to go

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

**Subtotal for Job #1: 0.00**

#### Job #2 - External

COMPLAINT: FRONT DOOR SIDE STAB JACK IS BENT.

CAUSE: Front stab jack is bent

CORRECTION: After inspection of the stab jack i seen that it was ben not so much the jack itself was more the mounting bracket. So i took the bracket off and straighted it up and put it back together. Annd lubricanted the jacks moving parts. Jack is working properly now. (Would advise customer that the T handle on his strong arm is missing) good to go

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

#### Parts

Part #	Description	Qty	Price	Total
314594	T-BOLT KIT, 2/PKG REPLACEMENT PARTS	1.00	N/C	N/C

**Subtotal for Job #2: 0.00**

#### Job #3 - External

COMPLAINT: FRONT ENTRY DOOR DRAGS AT THE BOTTOM AND IS HARD TO CLOSE

CAUSE: Front entry door dragging on the bottom



Customer #: 55939  
BREWER, KEVIN



CORRECTION: Inspection of the door i seen that it was dragging hard on the bottom. I adjusted the hing side of the door to give the off hing side more clearance. Door shuts properly now.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
<b>Subtotal for Job #3:</b>			<b>0.00</b>

**Job #4 - External**

COMPLAINT: INSTALL NEW STAB JACKS AT REAR OF CAMPER. THESE ARE ADD ONS FOR STABILITY.

CAUSE: Install new stab jacks on back of camper

CORRECTION: Took the 2 new stab jack and position them under the camper and drilled and bolted them to the frame. Jacks work properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts Part #	Description	Qty	Price	Total
285326	24IN SCISSOR JACK KIT WITH CRANK HAN	1.00	N/C	N/C
<b>Subtotal for Job #4:</b>				<b>0.00</b>

**Job #22V243 - Warranty**

COMPLAINT: RECALL 22V243 LP QUICK CONNECT

CAUSE: Recall lp quick conect

CORRECTION: Took old quick conect off. Cleaned the threads applied liquid thread seal put new quick conect on. And checked for leaks. No leaks good to go

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50
<b>Subtotal for Job #22V243:</b>			<b>55.50</b>

Parts Total:	0.00
Labour Total:	55.50
Sublet Total:	0.00
Extras Total:	0.00
<b>WORK ORDER TOTAL:</b>	<b>55.50</b>


Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 27 Oct 2025

W/O: 77939



Customer #: 55939  
BREWER, KEVIN

