



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77947
Promised Date:
03 OCT 25

CUSTOMER WORK ORDER

WO #: 77947

Customer: 2998 - BRADFORD, RONALD
- 812-305-5101

Tag:

Author: BH

Location: 1027 BH TO CLOSE

Stock #: 11419

Stock Desc: 2025 TT KEYSTONE
SPRINGDALE 310BR

Chassis #: 4YDTSGR29S7100061

Serial #: 4YDTSGR29S7100061

Mileage:

Licence:

Invoice #:

Date In: 03 OCT 25

Promised: 09 OCT 25

Date Sched:

Completed: 27 OCT 25

Warr. Date: 09 OCT 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery and put monster seal in all 5 tires and put the correct air pressure in all 5 tires and put the monster seal stickers on camper. Exterior inspection looks good. Roof inspection found some voids in the sealer on the roof that i filled with dicor self-leveling. And then i found some on the corners that i filled with black Dicor. Roof good to go now. Adjusted the step so the stops hit more on frame. Awning fabric and hardware looks and works properly Awning lights work properly. Interior inspection hooked up to city water and flushed out all the lines. Stove works properly microwave works properly both refrigerators work properly ac works properly water heater works properly furnace works properly. Did my lp drop test on outside port with stove and furnace running cannot get regulator to adjust no adjustment left. Going to install a new regulator. Installed new regulator system works properly now. Installed a new register cover. Put water in the fresh tank and flushed out all the lines. Water pump works properly. Hot side of outside faucet is leaking parts request in for a faucet

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C
704494	Grill - Register - Floor - 4" x 10"	1.00	N/C	N/C
25012	1/4" COUPLER SAFETY PIN W/12" CHAIN	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT



Customer #: 2998
BRADFORD, RONALD



W/O: 77947
Promised Date: 09 OCT 25



Customer #: 2998
BRADFORD, RONALD



Parts				
Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #EQUALIZER1000 - Internal
COMPLAINT: INSTALL 1000# EQUALIZER HITCH

CAUSE: Install hitch work
New hitch setup and adjustment

CORRECTION: I installed the hitch brakets to the camper and put the rest of the hitch in side compartment
Leveled the camper then checked the ball height and matched the truck hitch. Connected the truck to the
camper and checked the ride level. Connected the 7-way, coupler, breakaway cable, and safety chains.
Tightened all hardware. Had tech JW do the setup while SR shadowed his work

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
710831	EQUALIZER 1000#/10000# ADJ. HITCH	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
Subtotal for Job #EQUALIZER1000:				0.00

Job #MONSTER - Internal
COMPLAINT: MONSTER SEAL IN ALL TIRES

CAUSE: Install monster seal

CORRECTION: Took out the valve core of each tire and put monster seal in all 5 tires. And then put valve
core back in and put correct air pressure in all 5 tires. And then i put the monster seal stickers on camper.
Good to go now

Labor				
Code	Description	Mechanic	Total	
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C	
Subtotal for Job #MONSTER:				0.00

Job #PARTS - Internal
LCI LADDER

Parts				
Part #	Description	Qty	Price	Total
6873	LIPPERT ON THE GO LADDER	1.00	N/C	N/C
Subtotal for Job #PARTS:				0.00

Job #1 - Internal
WASHBAY MAXXGAURD



Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: REGULATOR IS NOT ADJUSTING

CAUSE: Replace lp regulator

CORRECTION: Too, lines off old lp regulator. And put the line on the new lp regulator. Checked for leaks and found no leaks. New regulator good to go

Labor				
Code	Description		Mechanic	Total
Z990	MISCELLANEOUS REPAIR		JTW	54.00

Parts				
Part #	Description	Qty	Price	Total
06-0443	MEGR-253P LP REGULATOR 2-STAGE	1.00	74.14	74.14

Subtotal for Job #2: 128.14

Job #3 - Warranty

COMPLAINT: OUTSIDE KITCHEN FAUCET IS LEAKING AT THE HOT KNOB

CAUSE: Faucet leaked at the handle

CORRECTION: Replaced faucet and it doesn't leak and it works properly

Labor				
Code	Description		Mechanic	Total
Z990	MISCELLANEOUS REPAIR		JTW	90.00

Parts				
Part #	Description	Qty	Price	Total
680572	DF-PL700C-WT WHITE LAVATORY FAUCET	1.00	18.59	18.59

Subtotal for Job #3: 108.59

Parts Total:	92.73
Labour Total:	144.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	236.73

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Oct 2025

W/O: 77947
Promised Date: 09 OCT 25



Customer #: 2998
BRADFORD, RONALD

