



KEYSTONE

Pre-Authorization

Pre-Authorization number	PREAUTH295 94 (PA03923307	Reference no.77954	Status	Approved
--------------------------	---------------------------------	--------------------	--------	----------

Serviceing Dealer 1194	Name Basden's American RV	Address 600 E Baseline Rd Evansville, IN 47725	VIN 4YDTSGP23T7100867	Retail sold on
------------------------	---------------------------	---	-----------------------	----------------

For paper claims only use one pre-authorization number per warranty claim form.
Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form.
The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.



KEYSTONE

Root	Approved Actual				Base		
Operation Description	Sublet	Sub Hours	Hours	hours	Qty	hours	Complaint/Cause/Correction
2300102A Entrance Door - Hinged - Repair	0	0.2	0.2		1	0.2	Complaint: ENTRY DOOR DOESN'T LATCH Cause: Entry door wont latch Correction: During pdi noticed entry door wouldn't latch. Door was bowed and wouldnt latch. Adjusted door and now latches
4152109B Refrigerator - GE Residential -Freezer Door	0	0.5	0.5		1	0.5	Complaint: SCRATCH ON FREEZER DOOR Cause: Scatxh on freezer door Correction: During pdi noticed a scratch on freezer door of fridge. Parts request submitted.
3102808B Dinette Table - Replace	0	0.3	0		1	0.2	Complaint: DISCOLORED MARKES ON THE KITCHEN TABLE Cause: Kitchen table has discoloration Correction: During pdi noticed kicthen table has discoloration in wood. Parts request submitted
6201106B Regulator - Replace	0	0.7	0.5		1	0.3	Complaint: LP REGULATOR IS BAD Cause: CANT SET IT Correction: During pdi lp drop test while doing 50% load could only get regulator to get 10wsi after bottoming out. Grabbed new regulator. Pigtails from old regulator would not come out without being rounded. Grabbed new pigtails. Attached pigtails to new regulator. Tightened down. Ran thread tap and attached regulator to chassis line. Attached to lp tanks. Turned on tank. Checked for leaks. Non found.

KRV – The submitted item is considered acceptable in regards to functionality and aesthetic appearance as stated in Keystone RV's Policy and Procedure Manual.

KRV -VCB

Pre-Authorization number: PREAUTH29594

1.2

For paper claims only use one pre-authorization number per warranty claim form. Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company.