

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2464194
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZTCFLS01TP432892
USA		CHASSIS VIN	1FDWE3FN3SDD32716
		MILEAGE	6008
		SITE/WAREHOUSE	210 / 210
Labor rate:	\$185.00	ITEM #	FLC27QBF35
OWNER INFORMATION		DEALER RO #	77967
CHUBBY CHOW FACTORY LLC		CLAIM START DATE	10/10/2025
PO BOX 3641		CLAIM END DATE	01/01/1900
Evansville, IN 47735			
USA			
Retail Date of Purchase	03/05/2025	WARRANTY EXPIRATION DATE	03/05/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	40-108-01-11-001337	Single Wall Switch - Electrical/110 Volt Interior/Replace/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-10-10 11:11:28 :: WIFI BLUE SWITCH IS FROZE UP. IT WAS ALSO CAUSING 5 AMP MONITOR PANEL FUSE TO BLOW. TODD DISCONNECTED WIRES AND FUSE QUIT BLOWING. Switch was sieged up and not switching. Switch is locked up and doesnt switch at all. Inspected the rooftop Wifi router and everything looks sealed and good. Requested new switch. Received new switch and installed out on lot. Turned disconnect on and tested switch and it illuminated and didnt blow any of the fuses.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			

Submitted	Labor Amt	\$37.00	Approved	Labor Amt	\$37.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$37.00		Total	\$37.00

DEALER	DATE	CUSTOMER	DATE
SIGNATURE		SIGNATURE	
I certify that I have performed these repairs consistent with Forest River Policies.		All repairs described have been inspected and are satisfactory.	