



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 77978  
Promised Date:  
24 OCT 25

### CUSTOMER WORK ORDER

WO #: 77978

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: BH  
Location: 1117 CHECK WORK

Stock #: 11644  
Stock Desc: 2026 TT FOREST RIVER  
CHEROKEE GREY WOLF 29NM  
Chassis #: 4X4TCKE27TK096786  
Serial #: 4X4TCKE27TK096786  
Mileage: 0  
Licence:

Invoice #:  
Date In: 07 OCT 25  
Promised: 31 OCT 25  
Date Sched:  
Completed: 19 NOV 25  
Warr. Date:

#### Job #CHECKTT - Internal

COMPLAINT: Transferred to BAS\*78365 on 05 NOV 25  
Estimate amount was 0.00  
CHECK IN NEW TRAVEL TRAILER  
TRAILER RETURNING FROM FACTORY FOR REPAIRS

CAUSE: Checkin

CORRECTION: Preformed check in and only found one cracked panel in overhead compartment in master bedroom. Filled out Paperwork.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
<b>Subtotal for Job #CHECKTT:</b>			<b>0.00</b>

#### Job #1 - Internal

COMPLAINT: Transferred to BAS\*78365 on 05 NOV 25  
Estimate amount was 0.00  
2 HR INSPECION UNIT CAME BACK FROM FACTORY

CAUSE: Checked on areas that was disassembled by factory to repair bent Frame.

CORRECTION: Turned LP on and hooked up my Manometer to verify Gas. Tested Stovetop and Furnace. Checked all 4 outside corners (inside and outside). Found a panel in the overhead that is not secured. Looked behind cabinets and seams on all 4 corners on the inside of unit. Found bent hinge under the master bed that opens for storage. Looked over all the seams on the ceiling from where roof was taken off. Went on roof and checked all the components and ch3cked the front and back caps. Found one spot on the rear doorside corner that had a opened void.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
<b>Subtotal for Job #1:</b>			<b>0.00</b>

#### Job #2 - Warranty

COMPLAINT: THE COVER HEAD COMPARTMENT IS BROKEN  
FROM TAKING IT APART AND NEEDS FIXED

Customer #: 1000  
BASDEN'S AMERICAN RV,



CAUSE: Damaged panel in overhead compartment.

CORRECTION: To replace the panel in over head compartment the whole overhead compartment must be removed. Removed the overhead doors. Removed the underbelly of Compartments trim. Removed the underbelly Compartment panel to reveal mount screws. Removed all the mount screws and 2 panels from unit. Cleaned all the old staples from panel and compartment base. Going to use the outer underbelly panel to replace the inner panel so i can go ahead and reinstall the over head panel. Panel measurements are 23 1/4in x 78in. Reinstalled overhead compartment.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	323.75

**Parts**

Part #	Description	Qty	Price	Total
F100692717	PANELING, 1/8" X 48" X 96" TAYLOR CH	1.00	53.35	53.35
F100716737	SEAM TAPE - 1.25" X 150' TAYLOR CHAM	1.00	22.53	22.53

**Other Services**

Code	Description	Qty	Price	Total
FRT	SEAM TAPE&PANEL	1.00	165.81	165.81

**Subtotal for Job #2: 565.44**

**Job #3 - Warranty**

COMPLAINT: THE WOOD FOR THE BED THAT FOLDS THE HINDGE IS BENT

CAUSE: Bent hinge

CORRECTION: Removed bent hinge from under master bed and took to table vise and straightened it out and reinstalled.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	37.00

**Subtotal for Job #3: 37.00**

**Job #4 - Warranty**

COMPLAINT: STEPS ARE RUSTED AND PAINT CHIPPING

CAUSE: Paint chipping and Rusting on Front Steps in multiple spots.

CORRECTION: Chipped away the loose paint, wire brushed the rust and painted with Black Gloss Paint.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	46.25

W/O: 77978  
Promised Date: 31 OCT 25



Customer #: 1000  
BASDENS AMERICAN RV,



Subtotal for Job #4: 46.25

**Job #5 - Internal**

COMPLAINT: SLIDE ROOM NOT GOING IN OR OUT

CAUSE: Issue with the Forktruck.

CORRECTION: While taking the unit out to the lot and opening it up the lights dimmed and slideout stopped working after about 6in out and them intermittently stopped. Brought back into the shop and hooked up to Shore power and it ran out properly with no issues... i ran it in and out 3 times.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #5: 0.00

Parts Total: 75.88  
 Labour Total: 407.00  
 Sublet Total: 0.00  
 Extras Total: 165.81  
**WORK ORDER TOTAL: 648.69**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 19 Nov 2025

W/O: 77978  
Promised Date: 31 OCT 25



Customer #: 1000  
BASDEN'S AMERICAN RV,

