

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2464413
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CABC8SK011654
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	203 / 203
OWNER INFORMATION		ITEM #	BCAT134RKX
TIMMY PHEGLEY		DEALER RO #	77987
12018 W 300 N		CLAIM START DATE	10/10/2025
Linton, IN 47441		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	10/10/2025	WARRANTY EXPIRATION DATE	10/10/2026

Claim Line Details

Labor

Line# 1	Operation Code 60-141-24-00-004307	Operational Description Shower Pan - Plumbing/Shower, Tub Surround/Repair/No Tread Code		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-10-10 12:53:11 :: SHOWER LEAKS Shower leaking Inspection of the shower found that the drain was hand tight and there was alot of flex in the shower pan. So i tightened up the fitting and i put shims under the shower pan supports. Checked it the next day and not leaks good to go			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$74.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$74.00
	Notes AUTHORIZED AS REQUESTED			

Labor

Line# 2	Operation Code 20-49-01-11-000591	Operational Description LED Light Strip - Front Cap - Exterior/Front, Fiberglass Cap, Cab Over/Replace/ Electrical		
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-10-10 12:53:58 :: THE LEDS ON THE FRONT OF THE TRIALER HAS MISSING LEDS TURNED ON THE LIGHTS ARE FOUND MISSING LEDS NEED TO REPALCE THE LED LIGHTS ON THE FRONT OF THE TRAILER			
Model#	Dlr Sub Hrs	1.20	Sub Labor Amt	\$222.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$74.00
	Notes TIME ADJUSTED-			

Submitted	Labor Amt	\$296.00	Approved	Labor Amt	\$148.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$296.00		Total	\$148.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.