



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77992
Promised Date:
10 OCT 25

CUSTOMER WORK ORDER

WO #: 77992

Customer: 56271 - BREEDLOVE, CRAIG
- 270-844-2583

Tag:

Author: BH

Location: DELIVERY 1010

Stock #: 11613

Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT 134BHX

Chassis #: 5ZT2CABCXSK011591

Serial #: 5ZT2CABCXSK011591

Mileage: 0

Licence:

Invoice #:

Date In: 08 OCT 25

Promised: 10 OCT 25

Date Sched:

Completed: 23 OCT 25

Warr. Date: 10 OCT 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final inspection before delivery that Jeremy failed to do

CORRECTION: Received a new battery from the parts department then put it in the battery box and connected the battery cables. Put the sewer hose in the front compartment. Generator was too big to fit in the camper left it with Ben. Turned the disconnect switch on then connected the test box to the 7-way and checked the brakes and breakaway switch and running lights. Checked and set the lug nuts to 110 ft-lbs and tires to 65psi. Ran the awning out and back in. Tested the tongue jack and coupler and cap lights. Checked the roof for cracks and voids then applied Dicor sealer as needed. Filled the fresh tank 1/3 full then had to dewinterize the camper. Connected the garden hose to the black tank flush to verify it works and then to the city water connection. Found packaging materials still in the fridge, smoke alarm, kitchen faucet, furnace, and microwave as they were not checked. Tested the smoke alarm, LP detector, furnace, and stove for operation. Checked the radio and test TV for signal. Noticed the bathroom door wouldn't shut because of the plastic door frame, got a job line to repair.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #PARTS - Internal

SEWER HOSE // GENERATOR

Parts

Part #	Description	Qty	Price	Total
4419	A074Z436 CUMMINS ONAN P4500i PORTABL	1.00	N/C	N/C
44722	DELUXE STARTER KIT	0.20	N/C	N/C

Subtotal for Job #PARTS: 0.00

Job #1 - Warranty

COMPLAINT: THE BATHROOM DOOR WILL NOT CLOSE

CAUSE: The plastic door frame was bowing from being too long.

CORRECTION: Took a picture of the door against the door frame showing that the door frame was in the



Customer #: 56271
BREEDLOVE, CRAIG



way. Unscrewed the plastic door frame trim, cut 1/8 off the bottom, and took a picture showing how much was cut. Screwed the door trim back on then took a picture showing that it help and cleared.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	37.00

Subtotal for Job #1: 37.00

Job #2 - Internal

DIFFERENCE BETWEEN A 10' KIT AND A STARTER KIT

Subtotal for Job #2: 0.00

Parts Total:	0.00
Labour Total:	37.00
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 37.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 23 Oct 2025

Customer Signature : _____

W/O: 77992
Promised Date: 10 OCT 25



Customer #: 56271
BREEDLOVE, CRAIG

