



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78009
Promised Date:
21 OCT 25

CUSTOMER WORK ORDER

WO #: 78009 (Appointment Date: 11 OCT 2025 - Time: 10:30am)

Customer: 55707 - MIDDENDORF, ERIC
- (812) 455-1466

Tag:

Author: GA

Location: 1117 CHECK STATUS WITH
BB

Stock #:

Stock Desc: 2022 5W KEYSTONE

RAPTOR 362

Chassis #:

Serial #: 4YDFRPT24NR801021

Mileage:

Licence:

Invoice #: 424492

Date In: 10 OCT 25

Promised: 31 OCT 25

Date Sched:

Completed: 17 NOV 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT THE SENSOR ON THE IN COMMAND IS SHOWING THE LEVEL FOR THE GENERATOR TANK ON THE TOY TANK AND THE LEVEL FOR THE TOY TANK ON THE GENERATOR TANK. CUSTOMER THINKS THE SENSORS ARE BACKWARDS

CAUSE: Found the wiring was reversed on the outside monitor.

CORRECTION: I corrected the wiring on the outside monitor and made sure it was reading inside for the genset. The tank is not full. It has maybe 2 inches of fuel in the bottom.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	5.40
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	262.80
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	196.20

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	41.81	41.81

Subtotal for Job #1: 506.21

Job #2 - External

COMPLAINT: INVERTOR SHOWING CODES.

CAUSE: I let unit run for several days in shop

CORRECTION: Only code i got was the low voltage code after a day of the refer running on inverter only.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

Subtotal for Job #2: 0.00

Job #3 - External

COMPLAINT: ALSO CHECK CONVERTOR TO MAKE SURE IT IS WORKING CORECTLY

CAUSE: Tested the output

CORRECTION: Onece hooked up to power the battery went from 12 volts to 13.59. Converter is working

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C



Customer #: 55707
MIDDENDORF, ERIC

Subtotal for Job #3: 0.00

Job #4 - External

CHECK TO SEE IF WARRANTY WILL COVER ANY OF THIS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: REPLACE THE ROOF VENTS

CAUSE: Turned in request for parts(installed front vent lid on 10/14)

CORRECTION: Installed 2 new vent lids

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	66.60
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	41.40

Parts

Part #	Description	Qty	Price	Total
11764	VENT LID ASSEMBLY FOR 4000K WHITE	1.00	56.52	56.52
40182	40182 PW VENT LID VENTLINE '08 UP	1.00	18.27	18.27

Subtotal for Job #5: 182.79

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterized

CORRECTION: Winterized unit ran antifreeze to bathroom faucet and shower and toilet. Then to kitchen sink and to the wash machine ports. There is no wash machine. I checked freezer for ice maker. And had no ice maker. I then ran through outside shower and opened the pop off on the water heater its tankless. Then i dumped the freah tank and all 3 sewer tanks.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	BRM	N/C
Z990	WINTERIZE UNIT	BRM	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	3.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #6 - Warranty

COMPLAINT: REPLACE THE ROOF UNDER WARRANTY

W/O: 78009
Promised Date: 31 OCT 25

Customer #: 55707
MIDDENDORF, ERIC


CUSTOMER THINKS THERE IS A SOFT SPOT IN
FRONT OF THE SOLAR PANEL. PLEASE
CHECK

CAUSE: The roof is soft. I fou d where
the roof looks torn in between the sewer
vent and the solar connector

CORRECTION: Sealed
spot on roof. Around sewer vent and the
solar connector. The roof is very soft
and dangerous in front of the solar
panels.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	266.40
Z990	MISCELLANEOUS REPAIR	BB	1,053.00
Z990	MISCELLANEOUS REPAIR	BB	54.00
Z990	MISCELLANEOUS REPAIR	BB	660.60
Z990	MISCELLANEOUS REPAIR	BB	748.80
Z990	MISCELLANEOUS REPAIR	BB	232.20
Z990	MISCELLANEOUS REPAIR	BB	766.80
Z990	MISCELLANEOUS REPAIR	BB	680.40
Z990	MISCELLANEOUS REPAIR	BB	739.80
Z990	MISCELLANEOUS REPAIR	BB	480.60
Z990	MISCELLANEOUS REPAIR	SAR	0.00
Z990	MISCELLANEOUS REPAIR	BB	750.60
Z990	MISCELLANEOUS REPAIR	BB	712.80
Z990	MISCELLANEOUS REPAIR	BB	414.00

Parts

Part #	Description	Qty	Price	Total
BRV102776	ATTIC VENT/PW - KEYSTONE	2.00	11.62	23.24
31-8490	40033 REPLACE ALL PLUMBING VENT	2.00	8.09	16.18
376374	Adhesive - Roof - 8010 - 1 Gal/Can	2.00	72.70	145.40
639157	Sealant - Lap Caulk - 5160 White - N	4.00	20.40	81.60
639155	Sealant - Self Leveling - 5121 Alpha	10.00	12.62	126.20
679920	Roof - Membrane - 9.5' x 45' - Alpha	1.00	572.35	572.35
3388	551LSB-1 BLACK NON SAG DICOR	1.00	8.72	8.72
500627	CLEAR SIKASIL PLUS	1.00	10.87	10.87

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SEALER	1.00	14.08	14.08
FRT	FREIGHT	1.00	153.93	153.93

Subtotal for Job #6: 8,712.57

Parts Total: 1,059.35
Labour Total: 8,132.40
Sublet Total: 0.00
Extras Total: 209.82
WORK ORDER TOTAL: 9,401.57

W/O: 78009
Promised Date: 31 OCT 25



Customer #: 55707
MIDDENDORF, ERIC



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 17 Nov 2025

W/O: 78009
Promised Date: 31 OCT 25



Customer #: 55707
MIDDENDORF, ERIC

