



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 78012
Promised Date:
24 OCT 25

CUSTOMER WORK ORDER

WO #: 78012 (Appointment Date: 11 OCT 2025 - Time: 01:30pm)

Customer: 56215 - DELP, TIMOTHY -
217-264-4650

Tag:

Author: GA

Location: 1114 CHECK STATUS WITH
CV

Stock #: 11609

Stock Desc: 2025 TT COACHMEN

CATALINA 293QBCKLE

Chassis #: 5ZT2CAUB0SN301650

Serial #: 5ZT2CAUB0SN301650

Mileage: 0

Licence:

Invoice #: 424377

Date In: 11 OCT 25

Promised: 31 OCT 25

Date Sched:

Completed: 12 NOV 25

Warr. Date: 27 SEP 25

Job #1 - Warranty

COMPLAINT: COUCH IS GLUED TO WALL AND WILL NOT PULL AWAY FROM WALL

CAUSE: Couch glued to wall

CORRECTION: Brought unit in. Plugged into shore power. Opened slideroom and went to couch to try to pull open. Ripped off wall and saw a silicone like substance had attached back of couch to wall. Had tore fabric off couch and attached to wall. Fabric and residue are stuck on wall panel and panel is torn up. Parts request put in for couch and panel

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	118.40
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	33.30
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	12.95
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	7.40
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	16.65
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	495.80
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

Parts

Part #	Description	Qty	Price	Total
F100410635	VINYL BOARD,F4E GABLE LATTE 3.6MM 7'	1.00	41.83	41.83
F100423366	20230035931 SOFA, 60" BIFOLD DANIEL	1.00	1,181.04	1,181.04

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - WALLBOARD	1.00	146.85	146.85
FRT	FREIGHT - SOFA	1.00	143.81	143.81

Subtotal for Job #1: 2,253.53

Job #2 - Warranty

COMPLAINT: REAR OUTSIDE SPEAKER DOESN'T WORK

CAUSE: Rear speaker wont work.

CORRECTION: Brought unit in. Turned on outdoor speakers. Front outdoor speaker works but rear wont turn on. Removed screws and cut silicone around speaker. Removed speaker from holding. Speaker has burn out on one end of connection. Requesting new speaker

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00



Customer #: 56215
DELP, TIMOTHY



Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Parts

Part #	Description	Qty	Price	Total
6309	SPEAKER, EXTERIOR JBL 6.5" STAGE 1,	1.00	29.69	29.69
PUTTY	PUTTY TAPE - ROLL	1.00	7.49	7.49

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SPEAKER	1.00	15.81	15.81

Subtotal for Job #2: 89.99

Job #3 - Warranty

COMPLAINT: OUTDOOR CABINET DOOR IS LOOSE AT HINGES

CAUSE: Cabinet door screws coming out.

CORRECTION: Opened outside kitchen door. Saw screws were falling out of door and had been stripped. Replaced with bigger diameter screws. Door holds and opens and shuts properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

Subtotal for Job #3: 55.50

Job #4 - Warranty

COMPLAINT: CABINET INSIDE OVER SINK ON THE LEFT IS LOOSE.

CAUSE: Door above sink loose.

CORRECTION: Went inside and saw left door above sink wouldnt shut all the way. Tried adjusting latch but latch was not holding like it should. Grabbed new latch. Set latch into place on door. Door now shuts tight and holds.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	18.50

Parts

Part #	Description	Qty	Price	Total
H201	H201 ROLLER CATCH WITH PRONG	1.00	5.06	5.06

Subtotal for Job #4: 23.56

Job #5 - Warranty

COMPLAINT: BLIND ON SLIDE WILL NOT STAY UP

CAUSE: Blind wont stay open.

CORRECTION: Went inside camper and found blind by table wont stay open. Wrap strip around tension point and blind now opens and stays open.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	9.25



Subtotal for Job #5: 9.25

Job #6 - Warranty

COMPLAINT: DOOR DRAGGING ON STEPS AND IS HARD TO CLOSE. DOOR ALSO DOESN'T SEEM RIGHT WHEN STEPS ARE UP

CAUSE: Door dragging stairs

CORRECTION: Brought camper in. Put stairs down saw they were dragging steps. Saw that steps were not pushed all the way to where there was a gap between threshold and steps. Reset step screws and secured in place. Adjusted step latches to door. That was hitting screen door. Adjusted screen door latch for door to lock into place. Adjusted striker plate for door to latch properly. Door no longer drags on steps.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

Subtotal for Job #6: 55.50

Job #7 - Warranty

COMPLAINT: PANEL UNDER THE BED SEEMS LOOSE AND MAY NEED TACKED UP

CAUSE: Panel loose under bed.

CORRECTION: Went inside bedroom and saw panel under bed had come loose. Lifted bed up and shoot staples in to secure panel to frame. Panel is now secure.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

Subtotal for Job #7: 37.00

Job #8 - External

UNDER WARRANTY. IF TECH FINDS ANYTHING ELSE HAVE GREG ADD JOBS

Subtotal for Job #8: 0.00

Job #WINTER - External

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterize

CORRECTION: Went inside unit. Found water pump. Turned valve off to fresh tank. Opened valve for winterize. Went to each water point and opened until pink came through. Dumped tanks. Opened pressure release valve on water heater and anode rod removed to dump water heater. Layed rod inside water heater door.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	CCV	N/C
Z990	WINTERIZE UNIT	CCV	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C



W/O: 78012
Promised Date: 31 OCT 25



Customer #: 56215
DELP, TIMOTHY



Subtotal for Job #WINTER: 0.00

Job #10 - External

STORAGE UNIT. PUT IN NO SPOT

Subtotal for Job #10: 0.00

Job #9 - Warranty

COMPLAINT: SCREEN DOOR IS TORN

CAUSE: Replace screen

CORRECTION: Screen was torn on screen door. Removed piceces holding screen in. Cut new screen to size. Instereted screen in door. Cut excess off of screen.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

Subtotal for Job #9: 37.00

Parts Total: 1,265.11
 Labour Total: 989.75
 Sublet Total: 0.00
 Extras Total: 306.47
WORK ORDER TOTAL: 2,561.33

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 Nov 2025

W/O: 78012
Promised Date: 31 OCT 25



Customer #: 56215
DELP, TIMOTHY

